
Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004 5. Lease Serial No.

SUNDRY	A MOLICES AND REPOR	(12 ON WEL	LS ALL THE	J. [Jicarilla 4	0 3			
Do not use thi abandoned we	is form for proposals to (bil. Use Form 3160-3 (APD)	12 CJ	the same of the sa	1	6. If Indian			Name	
		2004	11W 12 P		Jicarilla A				
SUBMIT IN TRI	IPLICATE - Other instru	ctions on rev	erse side 🧗	(O) F (S)	7/ If Unit o	r CA/Ag	reement, N	lame and/or No.	
1. Type of Well		16	A FARMINA	THE WATE					
Oil Well Gas Well	Signal Control of the			8. Well Name and No.					
2. Name of Operator			Charles Comments			Jicarilla 403 #1 (I-17)			
Benson-Montin-Greer Drilling Co				9. API Well No.					
3a. Address	3b. Phone No. (include area code)			30-039-21487					
4900 College Boulevard, Farming	505-325-8874			10. Field and Pool, or Exploratory Area					
4. Location of Well (Footage, Sec., T, R., M., or Survey Description)					Puerto Chiquito Mancos, West				
1900' FSL, 460' FEL, Section 17, Township 27 North, Range 1 West					11. County Rio Arrib				
12. CHECK APP	PROPRIATE BOX(ES) TO	INDICATE N	ATURE OF NO	OTICE, RE	PORT, O	R OTH	ER DAT	`A	
TYPE OF SUBMISSION									
	Acidize [Deepen	Prod	uction (Start/R	esume)	Πw	ater Shut-C	Off	
Notice of Intent	Alter Casing [Fracture Treat	=	amation	courie)	_	ell Integrity		
_	Casing Repair	New Construc	_	mplete			ther	,	
Subsequent Report		_	=	•		– 9			
Final Abandonment Notice		Plug and Abai		porarily Aban	don				
That Mondominent Notice	Convert to Injection	Plug Back	☐ Wate	r Disposal					
 MIRU RP Well Sevice. RU Be retailiner at 6875', squeeze Niobras Run CBL inside of 7" casing to at base of Pictured Cliffs at 3350', sack of cement) to cover Ojo Alar 	ra perfs with 50 sacks regular condetermine top of cement betwoods, set cement retainer at 3325', at	ement. Cut off 4 reen 7" casing an tempt to circulat	-1/2" casing at to d open hole below e back to surface	op of cement w 10-3/4" su . If successf	POH with rface casin ul, pump e	n 4-1/2" ng set at enough c	casing. 320'. Perfement (7.6)	f squeeze holes 65' fill-up per	
Alamo at 2900', set cement retained			0020 Willi 25 Buo.	ts coment, pe	ar addition	iai squoi	ozo notos c	loove ojo	
3. Perf additional squeeze holes a	at 370' (50' below bottom of sur	face casing), circ	culate cement to s	surface, leavi	ng cement		0,0		
4. Cut off 7" at 3' below ground level, set P&A marker, restore surface to original conditions.						ALBUGUERO			
WELLBORE SCHEMATIC ATTACHED						=	2	e et som e	
						i i			
						<u> </u>		-	
14. 1 hereby certify that the foregoing	g is true and correct	1				m	1.		
Name (PrintedlTyped)			les ·			Ξ	66		
Steve Owen			le Engineer			3.			
Signature Sove C	uon	Da	te June 14, 2004						
	THIS SPACE FO	R FEDERAL (OR STATE OFF	ICE USE					
Approved by (Signature) /s/ David R. Sitzler Name (Printed/Typed) Division of Name (Printed/Typed)						of M	ulti-Re	sources	
Conditions of approval, if any, are a certify that the applicant holds legal	or Office				Date JUL	3 0 2004			



CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator: BMG Drilling Corp. Well Name Jic 403, #1 (I-17)

- 1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. For wells on Federal leases, Alfonso Atencio with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748, ext 218. Office hours are 7:45 a.m. to 4:30 p.m.

For wells on Jicarilla leases notify Bryce Hammond with the Jicarilla Apache Tribe at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-1783 ext. 28.

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made:
 - A. A cement plug will be placed 50 feet above and below the 4½ inch casing stub.