Submit 3 Copies To Appropriate Distri	State	e of New Mexico	Form C-103
District I	Energy, Mine	erals and Natural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240)		WELL API NO.
District II 301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-045-32242	
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 8741	Λ	ta Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Sun		E-4426
87505			
	OTICES AND REPORT		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVOIR. USE "AF	OPOSALS TO DRILL OR TO	DEEPEN OR PLUTBACK TO A	
PROPOSALS.)	I LICATION FOR I LIGHT	(TORM'CAN) JOR SOCITY 3	State Com
1. Type of Well:		Au. Si	8. Well Number
Oil Well Gas Well	Other	10 Paul 2000	2A
2. Name of Operator		2 9/1 / W	9. OGRID Number
l		E ALLEN	006515
3. Address of Operator		100 mg mg	10. Pool name or Wildcat
P. O. Box 420, Farmington, NI	M 87499-0420		Blanco Mesaverde
4. Well Location		50201 01 11 01 9V	
		Colo Ula Lla Ser.	
Unit Letter <u>F</u> :_	1850 feet from the	e North line and 1850	feet from the <u>West</u> line
Section 16	Township 32		NMPM San Juan County
	11. Elevation (She	ow whether DR, RKB, RT, GR,	etc.)
A SECTION OF THE PARTY OF THE P		6305' GL	(Section Conference on the Con
Pit or Below-grade Tank Application			"
Pit Location: ULSectT	wpRngPit type	eDepth to Groundwa	terDistance from nearest fresh water well
Distance from nearest surface water	er Below-grade Tai	nk Location ULSect	TwpRng;
feet from theline a	nd feet from the	line	
			
		to Indicate Nature of Noti	
NOTICE OF	INTENTION TO:	S	UBSEQUENT REPORT OF:
	INTENTION TO:	S	UBSEQUENT REPORT OF:
NOTICE OF PERFORM REMEDIAL WORK	FINTENTION TO:	NDON REMEDIAL W	UBSEQUENT REPORT OF: ORK
NOTICE OF	INTENTION TO:	NDON REMEDIAL W	UBSEQUENT REPORT OF: ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON	FINTÊNTION TO: PLUG AND ABAN CHANGE PLANS	NDON REMEDIAL W	UBSEQUENT REPORT OF: ORK
NOTICE OF PERFORM REMEDIAL WORK	FINTÊNTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE	NDON SI REMEDIAL W COMMENCE CASING TEST	UBSEQUENT REPORT OF: ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	FINTÊNTION TO: PLUG AND ABAN CHANGE PLANS	NDON REMEDIAL W COMMENCE CASING TEST CEMENT JOE	UBSEQUENT REPORT OF: ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON	FINTÊNTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE	NDON REMEDIAL W COMMENCE CASING TEST CEMENT JOE	UBSEQUENT REPORT OF: ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION	SI REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C	UBSEQUENT REPORT OF: ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compared to the comp	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION ompleted operations. (C	SI REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compared to the comp	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION ompleted operations. (C	SI REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confidence of starting any propose	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION ompleted operations. (C	SI REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or conference of starting any propose or recompletion. Pressure test casing to 3000	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION ompleted operations. (Cd work). SEE RULE 11	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND Ompletion Some of proposed completion Attach wellbore diagram of proposed completion 4279'-4283'; 4290'-96'; 4298'-4302'; 4308'-15';
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53';	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION ompleted operations. (Cd work). SEE RULE 11 psi, held. Run GR-CCI 4356'-58'; 4360'-62'; 436	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND OMPletion Sometiment dates, including estimated date Attach wellbore diagram of proposed completion
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or conference of starting any propose or recompletion. Pressure test casing to 3000	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION ompleted operations. (Cd work). SEE RULE 11 psi, held. Run GR-CCI 4356'-58'; 4360'-62'; 436	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND Ompletion Some of proposed completion Attach wellbore diagram of proposed completion 4279'-4283'; 4290'-96'; 4298'-4302'; 4308'-15';
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53';	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION ompleted operations. (Cd work). SEE RULE 11 psi, held. Run GR-CCI 4356'-58'; 4360'-62'; 436	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND Ompletion Some of proposed completion Attach wellbore diagram of proposed completion 4279'-4283'; 4290'-96'; 4298'-4302'; 4308'-15';
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confessor of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14	FINTENTION TO: PLUG AND ABAN CHANGE PLANS MULTIPLE COMPLETION Ompleted operations. (Cd work). SEE RULE 11 Ppsi, held. Run GR-CCI 4356'-58'; 4360'-62'; 436 0,428# 20/40 sand.	REMEDIAL W COMMENCE CASING TES CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49)	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confessor of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the information of the starting are supported by the starting are su	CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPLET	REMEDIAL W COMMENCE CASING TES CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49)	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confessor of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the information of the starting are supported by the starting are su	CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPLET	REMEDIAL W COMMENCE CASING TES CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49)	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confessor of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the information of the starting are supported by the starting are su	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPLETION CHANGE PLANS CHANGE PLANS COMPLETION CHANGE PLANS COMPLETION CHANGE PLANS COMPLETION CHANGE PLANS COMPLETION CHANGE PLANS CHANGE PL	REMEDIAL W. COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49) Complete to the best of my knowledge of t	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND ABANDONMENT T AND ABANDONMENT Ompletion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion A279'-4283'; 4290'-96'; 4298'-4302'; 4308'-15'; holes). Acidize w/2000 gals 15% HCL. Frac w/ edge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan .
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confecting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the information of the proposed or confection.	CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPLET	REMEDIAL W. COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49) omplete to the best of my knowledge of the best of my knowledg	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or confecting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the information grade tank has been/will be constructed.	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPL	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49) omplete to the best of my knowled guidelines , a general perminent to the best of my knowled t	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT T AND ABANDONMENT T AND ABANDONMENT Ompletion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion A279'-4283'; 4290'-96'; 4298'-4302'; 4308'-15'; holes). Acidize w/2000 gals 15% HCL. Frac w/ edge and belief. I further certify that any pit or belowit or an (attached) alternative OCD-approved plan .
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the informate grade tank has been/will be constructed. SIGNATURE	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPL	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49) omplete to the best of my knowled guidelines , a general perminent to the best of my knowled t	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or c of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the informate grade tank has been/will be constructed. SIGNATURE	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPL	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49) omplete to the best of my knowled guidelines , a general perminent to the best of my knowled t	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or conference of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the information of the construction o	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPL	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49) omplete to the best of my knowled guidelines , a general perminent to the best of my knowled t	UBSEQUENT REPORT OF: /ORK
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or conference of starting any propose or recompletion. Pressure test casing to 3000 4342'-46'; 4349'; 4351'-53'; 146,730 gals slickwater; 14 I hereby certify that the information of the construction o	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION CHANGE PLANS MULTIPLE COMPLETION COMPL	REMEDIAL W COMMENCE CASING TEST CEMENT JOE OTHER: C Clearly state all pertinent details 03. For Multiple Completions: L logs. Perforate Mesaverde: 4 66'; 4372'-79' w/1 jspf (total 49) omplete to the best of my knowled guidelines , a general perminent to the best of my knowled t	UBSEQUENT REPORT OF: /ORK