UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5.	Lease Serial No.	
	NIMCEO78287	

6.	If Indian,	Allottee o	r Tribe Name

abandoned wer			/						
SUBMIT IN TRII	PLICATE - Other instruc	tions on reve	rse side.	5177070	7. If Unit or CA/Agreer	nent, Name and/or No.			
Type of Well Oil Well			Sep of	8. Well Name and No. HOWELL D 3A					
2. Name of Operator BURLINGTON RESOURCES	JONI CLARK 9:API Wel E-Mail: jclark@br-inc.com 30-045)-S1				
3a. Address PO BOX 4289 FARMINGTON, NM 87499	3b. Phone No. Ph: 505.326 Fx: 505.326			10/ Field and Pool, or Exploratory BLANCO MESAVERDE					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	n)	V2 3 0	- C Silve	11. County or Parish, as	nd State			
Sec 31 T31N R8W SWSE 090 36.84964 N Lat, 107.71309 W					SAN JUAN COU	NTY, NM			
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, R	EPORT, OR OTHER	DATA			
TYPE OF SUBMISSION			ТҮРЕ С	F ACTION					
Nation of Intent	☐ Acidize	□ Deep	en	Product	tion (Start/Resume)	☐ Water Shut-Off			
□ Notice of Intent	Alter Casing	☐ Fract	ure Treat	☐ Reclam	ation	☐ Well Integrity			
Subsequent Report	Casing Repair	□ New	Construction	☐ Recomp	olete	Other			
Final Abandonment Notice	Change Plans	□ Plug	and Abandon	Tempor	arily Abandon	Workover Operations			
J	Convert to Injection	□ Plug	· —		Disposal				
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 8/30/04 MIRU. SDFN. 8/31/04 RD HH, unseat pump. Remove stuffing box, laydown rods. Install stuffing box and RU hotoil unit. Hotoil tbg & rods. Reseat pump, load tbg & PT to 1500 psi. OK. POOH w/rods and pump. ND WH. NU BOP. Remove tbg hanger. SDFN. 9/2/04 Work stuck pipe. Land tbg in WH. RD. SDFN. 9/3/04 RU WL. RIH w/WL. Cut tbg @ 5714'. POOH. SD for holiday. 9/7 - 9/10/04 TIH w/fishing tools & tbg. POOH w/tbg. TIH to line top. SDFN. 9/13/04 TIH w/176 jts 2 3/8" 4.7# J-55 EUE tbg set @ 5686'. SN set @ 5673'. ND BOP. NU WH. RU to run rods. SDFN. 9/14/04 Blow well clean. TIH w/pump & rods. Set pump. PT to 500 psi. OK. RU pump jack, space out pump. RD. Rig released.									
14. Thereby certify that the foregoing is	strue and correct. Electronic Submission a For BURLINGTON Ri mmitted to AFMSS for pro-	ESOURCES OF	G CO LP, sent	to the Farmin	ngton				
Name (Printed/Typed) JONI CLA		Title REGULATORY SPECIALIST							
Signature (Electronic	Submission)		Date 09/15/	2004					
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE				
Approved By ACCEPT	ED		STEPHE _{Title} PETROL	N MASON EUM ENGIN	EER	Date 09/16/2004			
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to cond	ne subject lease	Office Farmin							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					nake to any department or	agency of the United			