UNITED STATES

DEPARTMENT OF THE INTERIOR

115

Sundry Notices and Reports on Wells	
<u> </u>	. /Lease Number
DEACHAS	NMNM111921
. Type of Well RECEIVED 6	. If Indian, All. or
GAS 070 FARMING YOR UM	Tribe Name
	. Unit Agreement Name
Name of Operator	
BURLINGTON (ASSOCIATION	
RESOURCES OIL & GAS COMPANY	
OCT	. Well Name & Number
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	Negro Canyon #100 API Well No.
For Box 4203, Full litting con, Am 0,433 (303) 320 3700 Significant	30-045-32505-00-X1
. Location of Well, Footage, Sec., T, R, M	0. Field and Pool
1305' FSL, 1035' FWL, Sec. 12, T31N, R8W, NAPM	Basin Fruitland Coa
	1. County and State
	San Juan Co, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTH	ER DATA
Type of Submission Type of Action	
Notice of Intent Abandonment Change of	
Z Subsequent Report Plugging Back Non-Routin	
Casing Repair Water Shut	off
Final Abandonment Altering Casing Conversion	to Injection
X Other - Cavitation	
	
3. Describe Proposed or Completed Operations	
B. Describe Proposed or Completed Operations 9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min	. OK. SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 4" open hole from 3397'-3515'.	. OK. SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 4" open hole from 3397'-3515'. TOOH w/bit. SDFN.	. OK. SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 4" open hole from 3397'-3515'.	
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ¼" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN.	hole to 3666'.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ¼" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830	hole to 3666'.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ¼" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN.	hole to 3666'.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ¼" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'.	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 %" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 %" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 %" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf,	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ½" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN.	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p PBTD @ 3828', 18' of
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 %" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 %" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 %" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf,	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ½" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mil 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/ . SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 %" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 %" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 %" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mill 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/ . SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ½" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mild 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p. PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/6. SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ¼" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mil 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201 released.	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/ . SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ¼" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mild 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p. PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/6. SDFN.
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ½" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mil 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201 released.	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p. PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/ . SDFN. ', test good. RD. Rig
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 4" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 4" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 4" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mil 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201 released.	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p. PBTD @ 3828', 18' of 1 1. TIH w/120 jts 2 3/8 . SDFN. ', test good. RD. Rig
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 ½" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 ½" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 ½" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mil 4.7# J-55 EUE 8rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201 released.	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p. PBTD @ 3828', 18' of 1. 1. TIH w/120 jts 2 3/8. SDFN. ', test good. RD. Rig
9/18/04 MIRU. ND WH. NU BOP. PT BOP & csg to 1500 psi/30 min 9/20/04 TIH w/bit. Drill 6 %" open hole from 3397'-3515'. TOOH w/bit. SDFN. 9/21/04 TIH w/bit. Drill from 3515' to TD @ 3830'. SDFN. 9/22/04 POOH w/bit. TIH w/underreamer. Underream 9 %" open TOOH w/underreamer. SDFN. 9/23/04 TIH w/underreamer. Underream from 3666' to TD @ 3830 w/underreamer. RU W/L. Run logs. RD. W/L. SDFN. 9/24 - 10/12/04 Blow well & CO to TD @ 3830'. 10/13/04 TIH w/12 jts 5 %" 15.5 K-55 LT&C liner set @ 3830'. perfed @ 3449-3492', 3537-3627', 3650-3673', 3719-3742', 2hpf, SDFN. 10/14/04 TIH w/perf mill. Mill perf plugs. TOOH w/perf mil 4.7# J-55 EUE &rd tbg set @ 3780'. SN @ 3757'. ND BOP. NU WH 10/15/04 TIH w/pump & rods. Run press gauge test, set @ 3201 released. 4. I hereby certify that the foregoing is true and correct.	hole to 3666'. '. TOOH Lnr top @ 3379'. Lnr p. PBTD @ 3828', 18' of 1. TIH w/120 jts 2 3/ . SDFN. ', test good. RD. Rig