Submit 3 Copies To Appropriate District	State of New M			Form C-103
Office District I	Energy, Minerals and Nati	ural Resources	<u>/</u>	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045-32536	
District III	1220 South St. Fi	rancis Dr.	5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM	87505	STATE 📙	FEE x
1220 S. St. Francis Dr., Santa Fe, NM 87505		11 12 13 10 75 A	6. State Oil & Gas	Lease No.
SUNDRY NOTICE	ES AND REPORTS ON WE	LLS AL S	7 Lease Name or I	Jnit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSITION OF THE PROPOSALS.)	SALS TO DRILL OR TO DEEPËN	OR PLUGUNACK TO A	Santa Rosa 32	sine rigiteement runne.
1. Type of Well:	[m		-8. Well Number	
Oil Well Gas Well X	Other	ON SON	2	
2. Name of Operator	V.	18.0	9. OGRID Number	
Energen Resources Corporati	ion	Alson and a significant	1629	028
3. Address of Operator		10C 0C 0C C	10. Pool name or V	Vildcat
2198 Bloomfield Highway - Farmington, NM 87401		Basin Fruitland Coal		
4. Well Location				
Unit Letter O:	840 feet from the Sc	outh line and	1855 feet from	n the <u>East</u> line
Section 32	Township 30N	Range 09w	NMPM	County San Juan
T. T. F. S. 1820	11. Elevation (Show whether			
<b>3.46</b> ,是最终的基础。	5	702' GL	- 44 · 44 ·	
Pit or Below-grade Tank Application	or Closure			
Pit type Depth to Groundwater _	Distance from nearest fre	sh water well Dis	stance from nearest surfa	ce water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	ebbls; Construction	on Material	
			· · · · · · · · · · · · · · · · · · ·	
10 (1 1 4	*	NT / CNT /*	D ( 0.1	D .
1) ( heck A	ppropriate Box to Indicat	A. Nightifa of Nightica	RANATT AT I ITHAT	I lata
•	• • •	· i	•	
NOTICE OF INTE	NTION TO:	· i	SEQUENT REP	ORT OF:
NOTICE OF INTE	• • •	· i	•	
NOTICE OF INTE	NTION TO:	SUB	SEQUENT REP	PORT OF: ALTERING CASING  PLUG AND
NOTICE OF INTE	NTION TO: PLUG AND ABANDON	SUB REMEDIAL WORK	SEQUENT REP	PORT OF: ALTERING CASING
NOTICE OF INTERPRETATION TEMPORARILY ABANDON DULL OR ALTER CASING	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB	SEQUENT REP	PORT OF: ALTERING CASING  PLUG AND  ABANDONMENT
NOTICE OF INTEPERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci	SEQUENT REP	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT
NOTICE OF INTERPRETATION TEMPORARILY ABANDON DULL OR ALTER CASING	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION   operations. (Clearly state all p	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spud ertinent details, and giv	SEQUENT REP	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION   operations. (Clearly state all p SEE RULE 1103. For Multip	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spud ertinent details, and giv	SEQUENT REP	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT
NOTICE OF INTER PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORAR	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12.	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spud ertinent details, and giv le Completions: Attach	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks C1	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   IX  uding estimated date proposed completion  24# J-55 casing, 4#/sk flocele (307)
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks Cl pm 11/07/04. Circulate 1	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   IX  uding estimated date proposed completion  24# J-55 casing, 4#/sk flocele (307)
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks Cl pm 11/07/04. Circulate 1	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   IX  uding estimated date proposed completion  24# J-55 casing, 4#/sk flocele (307)
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks Cl pm 11/07/04. Circulate 1	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   IX  uding estimated date proposed completion  24# J-55 casing, 4#/sk flocele (307)
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks Cl pm 11/07/04. Circulate 1	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   IX  uding estimated date proposed completion  24# J-55 casing, 4#/sk flocele (307)
NOTICE OF INTER PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks Cl pm 11/07/04. Circulate 1	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   IX  uding estimated date proposed completion  24# J-55 casing, 4#/sk flocele (307)
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30 Test casing & BOP to 600 p	CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Coment with 260 sks Cl pm 11/07/04. Circulate 1 si - ok.	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach 25" hole to 326'. It ass B, 5#/sk gilson 5 bbls. cement to a	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of the second sec	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT    Widing estimated date proposed completion  24# J-55 casing,  4#/sk flocele (307 purton. WCC. NU BOP.
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30 Test casing & BOP to 600 p	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks Cl pm 11/07/04. Circulate 1 si - ok.	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach 25" hole to 326'. It ass B, 5#/sk gilson 5 bbls. cement to a	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of a wellbore diagr	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   Widing estimated date proposed completion  24# J-55 casing,  4#/sk flocele (307 curton. WCC. NU BOP.
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30 Test casing & BOP to 600 p	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks Cl pm 11/07/04. Circulate 1 si - ok.	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spud ertinent details, and giv ele Completions: Attach 25" hole to 326'. It ass B, 5#/sk gilson 5 bbls. cement to a	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of a wellbore diagr	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   Widing estimated date proposed completion  24# J-55 casing,  4#/sk flocele (307 curton. WCC. NU BOP.
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30 Test casing & BOP to 600 p	NTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12. Cement with 260 sks cl pm 11/07/04. Circulate 1 si - ok.	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach 25" hole to 326'. It ass B, 5#/sk gilson 5 bbls. cement to a	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of a wellbore a wellbore and belief. I further a cor an (attached) alter a Assistant welchaghe@energen	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   widing estimated date proposed completion  24# J-55 casing, 4#/sk flocale (307 curton. WCC. NU BOP.  certify that any pit or below-mative OCD-approved plan  DATE 11/10/04 com hone No. 505-325-6800
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30 Test casing & BOP to 600 p  I hereby certify that the information ab grade tank has been/will be constructed or cl. SIGNATURE  Type or print name Vicki Donaghey  For State Use Only	CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12.  Cement with 260 sks Cl pm 11/07/04. Circulate 1 si - ok.	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach 25" hole to 326'. It ass B, 5#/sk gilson 5 bbls. cement to a e best of my knowledge ies, a general permit TLE	SEQUENT REP  ING OPNS.   e pertinent dates, include wellbore diagram of a wellbore diagr	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT   widing estimated date proposed completion  24# J-55 casing, 4#/sk flocale (307 curton. WCC. NU BOP.  certify that any pit or below-mative OCD-approved plan  DATE 11/10/04 com hone No. 505-325-6800
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  11/06/04 Spud well @ 1:00 set @ 321'. RU Halliburton cu.ft.). Plug down @ 8:30 Test casing & BOP to 600 p	CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state all p SEE RULE 1103. For Multip  pm 11/06/04. Drill 12.  Cement with 260 sks Cl pm 11/07/04. Circulate 1 si - ok.	SUB REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: spuci ertinent details, and giv ele Completions: Attach 25" hole to 326'. It ass B, 5#/sk gilson 5 bbls. cement to a e best of my knowledg tes, a general permit TLEProduction- mail address:	SEQUENT REP  ING OPNS.   e pertinent dates, include the wellbore diagram of the wellbore and belief. I further the or an (attached) altern Assistant velonaghe@energen Telepitor, OIST.	PORT OF: ALTERING CASING  PLUG AND ABANDONMENT    Widing estimated date proposed completion  24# J-55 casing,  4#/sk flocale (307 curton. WCC. NU BOP.   Certify that any pit or below-mative OCD-approved plan  DATE 11/10/04