Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
bandoned well. Use form 3160-3 (APD) for such proposals.

	NMSF078305 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. NMNM78415A							
Do not use thi abandoned wel								
SUBMIT IN TRII								
1. Type of Well	8. Well Name and No.							
	0 100							
CONOCOPHILLIPS COMPAN	IY	E-Mail: CHRIS	TINA.GUSTARTI	s@conoco	PHIL BOP639024342- 0	0-51 3003921342		
3a. Address P O BOX 2197 WL 6106 HOUSTON, TX 77252	Do not use this form for proposals to drill or to re-enter and abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other Instructions on reverse side. 7. Huntor CA/Agreement, NMMM78415A 7. 1. Williams and No. 3 29-5 21A 7. Williams and No.							
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	i)			11. County or Parish,	and State		
					RIO ARRIBA CO	DUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION			TYPE O	F ACTION				
Nation of Intent	☐ Acidize	Deepen		Production (Start/Resume)		☐ Water Shut-Off		
-	_	□ Frac	ture Treat	☐ Reclama	ation	☐ Well Integrity		
Subsequent Report	Casing Repair	□ New	Construction	Recomp	lete	Other Workover Operations		
☐ Final Abandonment Notice	Change Plans	☐ Plug and Abandon		☐ Tempor	arily Abandon	Workover Operations		
-	, — · — — · — —		Back	□ Water D	Disposal			
If the proposal is to deepen directions Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al	ally or recomplete horizontally, rk will be performed or provide operations. If the operation re- pandonment Notices shall be fil	give subsurface the Bond No. or sults in a multipl	locations and meas of file with BLM/Ble completion or rec	sured and true ver A. Required su completion in a	ertical depths of all pertir bsequent reports shall be new interval, a Form 316	nent markers and zones. filed within 30 days 60-4 shall be filed once		
Well was cleaned out and tub	ing changed. End of tubir	ng is now @ 5	835.15'. Daily	summary is a	ttached.			
					OCTOS STATES	10 10 10 10 10 10 10 10 10 10 10 10 10 1		
14. I hereby certify that the foregoing is	Electronic Submission #				System			
	nitted to AFMSS for proces	sing by MATT	HEW HALBERT	on 12/09/2004	•			
Name (Printed/Typed) CHRIS GUSTARTIS			Title AUTH	ORIZED REF	RESENTATIVE			
Signature (Electronic S	Submission)		Date 11/09/2	2004				
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE			
Approved By ACCEPT	ED		MATTHE TitlePETROL	W HALBERT EUM ENGINI		Date 12/10/2004		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conditions.	uitable title to those rights in the	Office Farmin	gton					

SAN JUAN 2		gudicationide Marigalitza		\$1.4.4.0 (19.5) [http://did.org/	exchange with the same	Summar	y en all			ukansura samu Militariki di kalendari	hange
API/UWI 300392134200	County RIO /	ARRIBA	State/Provir NEW ME	EXICO	NMPM-2	pal Location 29N-05W-08-O		N/S Dist. (ft) 799.9	N/S Ref. S	E/W Dist. (ft) 1460.0	EW Ref. E
Ground Elevation (ft) 6660.00)	Spud Date 06/16	6/1977	Rig Release Da 06/24/		Latitude (DMS) 36° 44' 5.9604	" N		Longitude (DMS) 107° 22' 34.3	3128" E	
Spromorphia and common	56329076179 9 11	s de la	or control x ips		e e e e e e e e e e e e e e e e e e e		· · · · · · · · · · · · · · · · · · ·	NAMES OF STREET	respectations are a	DENTAL PROPERTY OF THE	e bija sojajajajaja karanja
Start Date 10/01/2004 09:00	equipment Hot Work F	from SJ 2 Permit to re	9-5 #63; Spair floor or	ot; Rig up. n rig 30 & in	Checked stall ladde	well area for LE r hanger on BO	l when riggin L, H2S, & O2 P skid. Contir	2; held safe nue to rig up	ty brief; assiç o. Secure We	ned firewato	ch. Issued
10/04/2004 07:00	Blow down low; 2200 out: length Start Air; B Tally & cal PBTD, call	n casing: 10 psi high. P off - ND to egin Clear culate top it good. Go	60 psi, and Pipes: 300 psi BOP's; Pul nout to PBTI of fill was @ot hard tag,	tubing: 150 si low; 2300 lled 2-way. D. Got hard ② 5860' (12 made mark	psi. Kill tu Dpsi high. Nipple bac tag, made ' perfs cov . LD Tag jo	azards & how to bing & install 2- All Good. Had ok up to slips; pictor mark. LD Tag journed points & TOH: Streery Stand. Secu	-way check; Noressure - Work up singles to to 5881' rapping, tallyir	NU BOP's. I lood Group ; RIH & tag Strapping, - Hard Tag ng & inspect	Pressure Tes attempts to I @ estimated tallying & ins (9' below bo	t BOP's. Blir ubricate 2-w 5865' + Ri pecting all tul ttom perf.) L	nds: 240 psi ay check g up Hose; bing. Add acked 23' to
10/05/2004 09:00	Held pre-jo casing: 15 Thundersto LAND 188	ob safety n 0 psi. Con orm to pas: JT. 2 3/8" 1	neeting w/ o tinue drifting s. Kill casing	crew. Discu g in w/ 2 3/8 g w/ 10 bbl. T @ 5835.19	ssed job I 8" tubing. ND BOP's	nazards & how Layed down 13 NU Well Head F 1.78 'F' PROF	to avid them: bad joints & I.	: Landing tu replaced w	/ 13 good joi		
10/06/2004 07:00											