Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

	DEPARTMENT OF THE			,		Expires Novemb	er 30, 2000
	BUREAU OF LAND MAN	IAGEMENT			5. Lease	Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS					14-20	-603-2	037
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					n, Allottee or 7		
abandoned well. Use Form 3160-3 (APD) for such proposals.							
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				7 July 1980 200 18 (1970)	Nava	<del>/</del>	
SUBMIT IN TE	IPLICATE - Other inst	ructions on	reverse sid	e	7. If Unit	or CA/Agreem	ent, Name and/or No.
		A series of the			Horse	shoe G	- 11
1. Type of Well					1 3 €	3406	4110
2. Name of Operator Vulcan	Other WIW					ame and No.	
2. Name of Operator Vulcan	Minerals + Energy		an arian	Silvenin	107		
- 10 NIMOCI)	·		<u></u>	- 5 6 D	9. API W		
	Brazos Rd.	3b. Phone	No. (include area	code) O		10502	
Azree, A	Jm 87410		6/78		10. Field a	nd Pool, or Exp	loratory Area
4. Location of Well (Footage, Sec		on)	$-f^{i,j} = e^{it}$	7 200g =	Horse	or Parish, State	مره ال
Sec. 24, T. 3	UN., R. 17W.,		BI CK		11. County	or Parish, State	e ,
Class			*		San	),,,,	Nm
660/5-	3300/E		Paris our		<i>y</i>		
12. CHECK AF	PPROPRIATE BOX(ES) T	O INDICAT	<del></del>	<del></del>	PORT, O	R OTHER D	PATA
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION			
	Acidize	Deepen		Production (Start/	Resume)	■ Water Si	nut-Off
Notice of Intent	Alter Casing	Fracture	Treat	Reclamation		Well Into	grity
Subsequent Report	Casing Repair	New Con	struction	Recomplete		Other	
Subsequent Report	Change Plans	Plug and	Abandon 🔲	Temporarily Aban	ndon	_	
Final Abandonment Notice	Convert to Injection	Plug Back	k 🗀	Water Disposal			
13. Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Fit determined that the site is ready	ctionally or recomplete horizonts ne work will be performed or prolived operations. If the operational Abandonment Notices shall for final inspection.)	ally, give subsur ovide the Bond on results in a m be filed only aft	face locations and No. on file with I ultiple completion	I measured and true BLM/BIA. Require or recompletion in	vertical dep d subsequen a new inter	ths of all pertin t reports shall I val, a Form 316	ent markers and zone be filed within 30 day 50-4 shall be filed onc
See arriched	plugging proced						• •
	The Jan & Process	ore.					
				•			
	·						
•							
							•
	* .						
14. I hereby certify that the foregoin	g is true and correct				<del></del>		
Name (Printed/Typed)	<b></b>		l				
Nmoco Co	ontract Pluggi	1 (	Title				
		7			<del></del>	· · · · · · · · · · · · · · · · · · ·	
Signature Alias A - A			Data	(/4/0:	•		

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Original Signed: Stephen Mason
Approved by

does not warrant or

JUN 0 4 2003

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

API WELL # Well Name Well # Operator Name Type Stat County UL Sec Twp N/S Rng W/E Feet NS Ft EW Order\_No 30-045-10502 HORSESHOE GALLUP UNIT 107 PLAYA MINERALS & ENERGY INC I A San Juan N 24 31 N 17 W 660 S 3300 E

R-2210

api\_number status csg\_1 csg\_1q csg\_1d csg\_2 csg\_2q csg\_2d csg\_3 csg\_3q csg\_3d liner\_size liner\_quan tubing t\_set\_dept csg\_perf 30-045-10502 WI 8 5/8 107 100 5 1/2 1501 100 2 3/8 1450 1422-39

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scrapper if required,

RIH Set CIBP 1325 ', cap with 296 'cement.

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ 157 '+ - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location

WELL NAME 107 HGU SEC, TWN, RNG. 24-31N-17D

Mesavirde Poiar Lookour Mancos	31'	85/8" 32#  107'  Plug 157 - 50/kce  157/ 7.483(1.18) = 18 50;  50/ 5.7719(1.18) = 7 565  167/ 5.643(1.18) = 16 383
		41 3xs
Gallop	1079	$-\frac{1}{(325-1029)+50.7.983(1.18)=39 s_{KS}}{(325-1029)+50.7.983(1.18)=39 s_{KS}}$ $-\frac{1}{(325-1029)+50.7.983(1.18)=39 s_{KS}}{(600)}$
		150/'

JUKFACE CA	SING
SIZE HOLE	
SIZE CASING	
Annilar Volume	f+3/c
Cement _	/ <del>//.</del> SK
Volume -	$-ft^3$

SIZE HOLE" SIZE CASING" Annulur Volume f Cement s	INTERMEDIATE	CASINE
Valorine 4	SIZE CASING - Annuar Volume	