Submit 3 Copies To Appropriate District Office	State of				Form C-103 Revised March 25, 1999					
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals	irai Resources	WELL API NO.							
<u>District II</u> 811 South First, Artesia, NM 87210	OIL CONSERV	30-045~								
District III	5. Indicate Type of Lease STATE FEE									
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	6. State Oil & G									
1220 S. St. Francis Dr., Santa Fe, NM 87505										
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.) 1. Type of Well: Oil Well Gas Well	ALS TO DRILL OR TO DEEF	PEN OR PLU	UG BACK TO A		Unit Agreement Name:					
2. Name of Operator	8. Well No. 228									
P/AYA minelals 3. Address of Operators		•		9. Pool name or Wildcat						
/ CARC	of OCL	PAZ	tec	3. 1 ooi name or v	Vildeat					
4. Well Location										
Unit Letter 3 :	660 feet from the	N	line and/	1980 feet from	n theline					
Section 02	Township J 10. Elevation (Show w	O NRa whether D	ange 16 W R, RKB, RT, GR, etc	NMPM	County					
	opropriate Box to Inc	dicate Na								
NOTICE OF INT PERFORM REMEDIAL WORK ☐		×	SUB REMEDIAL WOR	SEQUENT REI K □	PORT OF: ALTERING CASING □					
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS. 🔲	PLUG AND ABANDONMENT					
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ND	ADANDONWENT					
OTHER:			OTHER:							
12. Describe proposed or complete of starting any proposed work). or recompilation.										
SEE ATTACK	he d			1753 1153	700					
				A Co	2003					
				E. C.						
				**************************************	TO COLLEGE					
					- Linder					
I hereby certify that the information	above is true and comple	ete to the	best of my knowled	ge and belief.						
SIGNATURE CHARISE PCK	_		,		DATE					
Type or print name				Telep	hone No.					
(This space for State use)	1		DEPUTY ON R GA	s inspector, dist						
APPPROVED BY Nas-	The	_TITLE	- encor 6-18 (+4/1)	- nablefill begi	JUN -6 2003					

API WELL #	Well Name	Well #	Operator Name	Тура	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/E	Feet	NS	Ft	ΕW	Order_No
1 -	HORSESHOE GALLUP UNIT		PLAYA MINERALS & ENERGY INC	0		San Juan	Sv	3	2	30	N	16	W	660	Z	1980	W	

status	csg_1	csg_1q	csg_1d	csg_3	csg_3q	csg_3d	tubing	t_set_dept	csg_perf
CO	9 5/8	102	100S	5 1/2	1692	100S	2 3/8	1630	1587-
									1621

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scrapper if required,

RIH Set CIBP 1530, cap with 200 'cement.

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ 152 '+ - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location

Set Plug 350 - 200