

30-045-11336
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.LEASE DESIGNATION AND SERIAL NO.
UTE MOUNTAIN TRIBE LEASE
1-22-IND-2495 2772
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
UTE MOUNTAIN TRIBE OF
INDIANS

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR SOUTHERN UNION PRODUCTION COMPANY		8. FARM OR LEASE NAME BARKER DOME	
3. ADDRESS OF OPERATOR P. O. Box 808, FARMINGTON, NEW MEXICO		9. WELL NO. 7	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310 FEET FROM SOUTH LINE AND 660 FEET FROM THE EAST LINE.		10. FIELD AND POOL, OR WILDCAT BARKER DOME	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T-32-N, R-14-W		12. COUNTY OR PARISH SAN JUAN	
14. PERMIT NO.		13. STATE NEW MEXICO	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6204 DERRICK FLOOR			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WE PROPOSE TO PLUG AND ABANDON WELL AS FOLLOWS.

1. SET CEMENT PLUG OVER DAKOTA FORMATION FROM TOTAL DEPTH 2377 TO 2200 FT. USING 30 SACKS REGULAR CEMENT.
2. FILL 5-1/2" CASING W/9.0# DRILLING MUD FROM 2200 FT. TO 500 FT.
3. PERFORATE SQUEEZE HOLES IN 5-1/2" CASING AND CIRCULATE CEMENT TO SURFACE USING 250 SACKS REGULAR CEMENT.
4. SET 5 SACKS CEMENT PLUG IN TOP OF 5-1/2" CASING FROM SURFACE TO 37 FT.
5. ERECT DRY HOLE MARKER AND ABANDON WELL.



18. I hereby certify that the foregoing is true and correct.

SIGNED **GILBERT D. NOLAND, JR.**TITLE **DRILLING SUPERINTENDENT**DATE **JULY 30, 1964**

(This space for Federal or State office use)

TITLE

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

JUL 31 1964

JERRY W. LONG
DISTRICT ENGINEER

*See Instructions on Reverse Side.

RECEIVED

JUL 31 1964

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.