Form 3160-5' (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO 1004-0135 Expires. July 31, 2010

5.	Lease Serial No	
	NMSF078902	

abandoned well. Use form 3160-3	6 . If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other ins	7 If Unit or CA/Agreement, Name and/or No NMNM97716			
Type of Well	HANE	8 Well Name and No GALLEGOS CANYON UNIT 63		
2 Name of Operator Contra BP AMERICA PRODUCTION CO. E-Mail hlava	9. API Well No. 30-045-06884-00-S2			
3a Address 200 ENERGY COURT FARMINGTON, NM 87401	3b Phone No (include area code) Ph: 281.366.4081	10 Field and Pool, or Exploratory BASIN FRUITLAND COAL		
4 Location of Well (Footage, Sec., T., R., M, or Survey Description	ription)	11 County or Parish, and State		
Sec 5 T27N R12W SWNE 1650FNL 1650FEL 36.606920 N Lat, 108.131060 W Lon		SAN JUAN COUNTY, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				

TYPE OF SUBMISSION			ТҮРЕ О	F ACTION	
ىك	Notice of Intent Subsequent Report Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off □ Well Integrity □ Other

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BP has evaluated the above mentioned well and finds no further uphole potential.

BP respectfully requests permission to plug & abandon the entire wellbore per the attached procedure

Notify NMOCD 24 hrs prior to beginning operations

	,	22232425262		
e.	So.	37,	1282	
	17 18	RECEIVED	93031	
	91.51	OIL CONS. DIV. DIST 3	7	
	186	3511101 68 F 3 CA	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
-101 98 Fa				

14 Thereby certify that the foregoing is true and correct. Electronic Submission #111204 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO., sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 06/23/2011 (11SXM0524SE)						
Name (Printed/Typed)	CHERRY HLAVA	Title	REGULATORY ANALYST			
Signature	(Electronic Submission)	Date	06/22/2011	,		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By STEPHEN MASON		TitleF	PETROLEUM ENGINEER	Date 06/23/201		
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon			: Farmington	•		
T. J. 10 H.C. C. C 100	1 17 1 10 11 0 0 0 1 10 10 1 1 1 1 1 1		1 1 110 11 . 1 . 1	Cal II a l		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

bp

BP - San Juan Wellwork Procedure


GCU 63 30-045-06884

Unit letter G SEC. 05, T27N, R12W 1650' FNL, 1650 FWL San Juan, NM Fruitland Coal Formation OGRID Number: SF 078902 P&A date – TBD

Basic Job Procedure:

- 1. Pull rods (if necessary) and tubing
- 2. Set Bridge Plug ~ 1214'
- 3. Load hole and run CBL
- 4. Place cement plugs
 - > PBTD (1529') surface (over CIBP, Picture Cliff, Fruitland, Kirtland, Ojo, and Shallow zones)
 - Reports from original completion state that cement was circulated to surface on the surface string and cement was circulated to surface on the production casing. According to well reports, all zones are contained behind pipe. We will confirm with a CBL and attempt to squeeze if necessary
- 5. Install well marker and identification plate per regulatory requirements. RD MO Location

Current Wellbore Diagram



Proposed Wellbore Diagram

