



To: E. Premo
Geologist
New Mexico Oil Conservation Division

Date: 7/15/2011

From: Ben Mitchell
Regulatory Specialist

Well Name: Rosa Unit 399A

Subject: Footages to Section Lines on C-102

Elizabeth,

The as drilled C-102 for the Rosa Unit 399A which was submitted earlier this week shows footages which are conflicting when compared to the survey report for the same well. This is due to the north and east section line being 1 degree and .5 degree off respectively. Our surveyor, Jason C. Edwards, has located GLO caps at the section corners and quarter section corners (Section 31) and provided the footages in question based on field survey results. These results show a difference in footages approximately 40' off north and 16' off east.

To recap and go into greater detail, the north section line is about a degree off to the south moving from east to west and the east section line is approximately .5 degree off to the west moving south to north. The end result is the smaller footage distance from the end of lateral to both the north and east line.

In addition, the surface location was surveyed and the footages are correct in relation to the aforementioned section corner GLO caps.

Thank you,

Ben Mitchell
Regulatory Specialist

WPX
505-634-4206
505-947-4975
ben.mitchell@williams.com

OIL CONS. DIV.



RCVD JUL 15 '11