In Lieu of Form 3160 (June 1990)

UNITED STATES DEPARTMENT OF INTERIOR **BUREAU OF LAND MANAGEMENT**



FORM APPROVED Budget Bureau No 1004-0135 Expires March 31, 1993

SUNDRY	NOTICE	AND	REPORTS	ON	WELLS
SUNDKI	MOTICE	ΔU	KEI OKIS	OI.	W LLLS

JUL 05 2011

Lease Designation and Serial No. NMSF-078890

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals Farmington Field Office

TO DRILL" for permit for such proposals

Bureau of Land Manage nem

If Indian, Allottee or Tribe Name

	SUBMIT IN TRIPLICATE	7.	If Unit or CA, Agreement Designation Rosa Unit
1	Type of Well Oil Well X Gas Well Other	8.	Well Name and No. Rosa Unit #288
2	Name of Operator WILLIAMS PRODUCTION COMPANY	9	API Well No. 30-039-25293
3.	Address and Telephone No PO Box 640 Aztec, NM 87410-0640	10	Field and Pool, or Exploratory Area Basin Fruitland Coal
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 1840' FSL & 1020' FWL Sec 04 (L), T31N, R4W	11.	County or Parish, State Rio Arriba, New Mexico

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	Тү	/PE OF ACTION
X Notice of Intent	Abandonment	Change of Plans
a	X Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection
	Other Bradenhead Repair	Dispose Water
		(Note: Report results of multiple completion
		on Well Completion or Recompletion Report
		and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Objective: Re-Frac Fruitland Coal

- 1) MIRU, kill, ND tree, & NU BOP's.
- 3) TOOH w/ tubing.
- 4) Cleanout to PBTD @ 3940'.
- 5) Set plug & test casing.
- 6) Change out wellhead to frac head.
- 7) Retrieve plug & lay down tubing.
- 8) Re-Frac the following Fruitland Coal intervals: 3866'-3876' 3850'-3854' 3805'-3811'
- 9) Change out frac head to wellhead.
- 10) TIH w/ tubing.
- 11) ND BOPs, NU tree, RDMO.



14.	I hereby certify that the foregoing is true and correct Signed Ben Mitchell	Title Regulatory Specialist Date 6/5/2011			
	(This space for Federal or State office use) Approved by Original Signed: Stephen Mason	Title	Dia	JUL 0 6 2011	
	Conditions of approval, if any	Title	Dåte _		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.