

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	BP America Production Company	Contact	Jeff Peace
Address	200 Energy Court, Farmington, NM 87401	Telephone No.	(505) 326-9479
Facility Name	ATLANTIC A LS #5B	Facility Type	Active gas well API# 3004530059
Surface Owner	Federal	Mineral Owner	Federal
		Lease No	NM0606

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	26	31 0N	10.0W	1865	South	690	East	San Juan

Latitude 36.867573 Longitude -107 845627

#### NATURE OF RELEASE

Type of Release	Produced water and condensate	Volume of Release:	Unknown	Volume Recovered:	0
Source of Release	300 bbl production tank	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	06/29/11 - 11 00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully \*

Describe Cause of Problem and Remedial Action Taken \*

BP construction crew was to conduct site equipment modifications in replacing the 300 bbl production tank with a 100 bbl tank. During preparation for the removal of the existing tank, lost integrity of its man way thief hatch was discovered. Impacted soils were observed beneath tank being replaced. Gas well shut in and no further production of gas or fluid by-products occurred up to the present time. June 27, 2011, excavation was conducted to establish vertical and lateral extent of impacts (unsuccessful).

Describe Area Affected and Cleanup Action Taken \*

Area affected appears to be directly below production tank to an unknown depth. Will address both lateral and vertical extent with mobile drill rig. Thereafter, will adhere to 1993 spill and release guideline document along with gaining remediation approval from district office prior to commencement.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature	<i>Jeffrey H. Peace</i>	OIL CONSERVATION DIVISION	
Printed Name	Jeff Peace	Approved by District Supervisor	<i>Bd</i>
Title	Environmental Advisor	Approval Date	7/16/11
E-mail Address	Peace.Jeffrey@bp.com	Expiration Date	
Date	7/1/2011	Conditions of Approval	WJK 1122341136
Phone	(505) 326-9479	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary