

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

**RECEIVED****AUG 15 2011**

## Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator

**ConocoPhillips**

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

Surface: Unit F (SENW), 1780' FNL &amp; 1840' FWL, Section 27, T30N, R11W, NMPM

Farmington Field Office  
Bureau of Land Management  
NM-02491

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

8. Well Name & Number  
Federal A 1

9. API Well No.

30-045-09192

10. Field and Pool  
Blanco MV / Basin DK

11. County and State  
San Juan, NM

**12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA**

## Type of Submission

## Type of Action

<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans	<input checked="" type="checkbox"/> Other –	<input type="checkbox"/> 2 <sup>nd</sup> Squeeze
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction		
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging	<input type="checkbox"/> Non-Routine Fracturing		
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off		
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection		

**13. Describe Proposed or Completed Operations**

ConocoPhillips would like to correct the Operator from Burlington Resources to ConocoPhillips on the NOI submitted 8/5/11 for this well.

8/5/11 ConocoPhillips ran a CBL after squeezing in the 5144'-5662' interval and detected it is still leaking. After the squeeze job authorized on 8/4/11, cement was detected from 5500'-5080'. Troy Salyers/BLM & Brandon Powell/OCD were contacted to request permission to perform another squeeze in an attempt to fix the leak. If the leak is not remediated CoP would like to set a CBP above the 5144'-5662' interval in order to repair a small leak that was detected at 750'. Both Troy & Brandon concurred with this request. A CBL will be submitted after the squeeze.

*if sqz from 5144-5662 does not remediate leak, additional remediation will be necessary.*  
14. I hereby certify that the foregoing is true and correct. *after leak at 750' is remediated.*

Signed

*Dollie L. Busse*

Dollie L. Busse

Title Staff Regulatory Technician

Date 8/12/11

(This space for Federal or State Office use)

APPROVED BY Original Signed: Stephen Mason

Title

Date

**AUG 16 2011**

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

**NMOCD**