Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

AUG 29 2011

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

5 Lease Serial No NO-G-9904-1348

6 If Indian, Allottce or Tribe Name

7 If Unit of CA/Agreement, Name and/or No

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or totre-enterganield Onic abandoned well. Use Form 3160-3 (APD) for such proposals anagen NA 059728

SUBMIT IN TRIPLICATE - Other instructions on page 2		7 If Unit of CA/Agreeme	nt, Name and/or No
1 Type of Well			
Oil Well Gas Well Other		8 Well Name and No Monroe 1	
2 Name of Operator D J Simmons, Inc		9 API Well No 30-045-30387	
3a Address 3b Phone No (include area code)		10 Field and Pool or Exploratory Area	
1009 Ridgeway Place, Suite 200 Farmington, NM 87401 (505) 326-3753		Gallegos S Fruitland Sandstone / PC	
4 Location of Well (Footage, Sec., T.R., M., or Survey Description)		11 Country or Parish, State	
Surface 1095' FSL & 679' FEL, SE/SE Section 19, T-26-N, R-11-W		San Juan County, New Mexico	
12 CHECK THE APPROPRIATE BOX(ES) TO INI	DICATE NATURE OF NOTI	CE, REPORT OR OTHER	DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
✓ Notice of Intent ☐ Acidize ☐ Deep ☐ Alter Casing ☐ Fract	Production (Start/Resume) Water Shut-Off ure Treat Reclamation Well Integrity		
Subsequent Report		omplete sporarsly Abandon	Other
Final Abandonment Notice Convert to Injection Plug	Back Wat	er Disposal	
Attach the Bond under which the work will be performed or provide the Bond following completion of the involved operations. If the operation results in a resting has been completed. Final Abandonment Notices must be filed only affectermined that the site is ready for final inspection.) • Move in and Rig Up well service unit. • Kill well as necessary with viscous fluid. • Trip out of hole and lay down rods, pump and production tubing. • Remove wellhead. • Secure well with 4 ½" X 2" swage and ball valve. • Move rig out. • Rig up cementing company to well. • Mix 30sx lead cement with 2%CaCl2, ½#/sx cellophane, 3#/sx gilsonite to 0 Do not displace cement. • Wash up equipment to water tank with 25# sugar added. • Wait overnight. • If cement is not at surface, tag and top with neat cement as necessary. • Dig out, cut off, install marker, remediate location as indicated in condition. Other sundries of intent to plug and abandon will be filed on additional wells for preparation and scheduling of additional wells.	nultiple completion or recompler all requirements, including the first state of the	pletion in a new interval, a Regreciamation, have been con	Form 3160-4 must be filed once impleted and the operator has a second se
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)			
Chris S Lopez	Title Regulatory Specialist		
Signature Cities S. CoPo?	Date 08/29/2011		
THIS SPACE FOR FEDI	ERAL OR STATE OF	FICE USE	
Approved by Original Signed: Stephen Mason	Title	Date	aug 3 0 2011
Conditions of approval, if any, are attached Approval of this notice does not warrant or that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon	ould Office		
Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any	person knowingly and willfully	to make to any department or	r agency of the United States any false,

fictitious or fraudulent statements or representations as to any matter within its jurisdiction