## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## RECEIVED

OCT 25 2011

	Sundry Notices and Reports on Wells		nington Field Office of Land Managemen
 l.	Type of Well GAS	5. 6.	Lease Number SF-078943 If Indian, All. or Tribe Name
2.		7.	Unit Agreement Name San Juan 29-7 Unit
	BURLINGTON RESCURCES OIL & GAS COMPANY LP		
3.		- 8.	Well Name & Number San Juan 29-7 Unit 46
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
-		-	30-039-23943
1.	Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1690' FSL & 1500' FEL, Section 6, T29N, R7W, NMPM	10.	Field and Pool Blanco Mesaverde
		11.	County and State Rio Arriba, NM
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT Type of Submission  X Notice of Intent  X Recompletion  Abandonment X Recompletion  New Construction	THER	DATA Other
	Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection		
13	Casing Repair Water Shut off	etting a	CBP 50' above the top
14.	Casing Repair Altering Casing Conversion to Injection  Describe Proposed or Completed Operations  The SJ 29-7 Unit 46A is within 50' of the twinned SJ 29-7 Unit 170 wellbore. Prior to Burlington Resources would like to prep the 46A wellbore by pulling out tubing and see	etting a	CBP 50' above the top arred with this request. ✓

NMOCD

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

Pc