

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

OCT 25 2011

FORM APPROVED  
OMB No. 1004-0137  
Expires March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NM-052931

6. Indian, Allottee or Tribe Name

Navajo

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No

Hanson # 36

9. API Well No

30-031-20720

10. Field and Pool, or Exploratory Area

South Hospah Field

11. County or Parish, State

McKinley County, New Mexico

## SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator Nacogdoches Oil &amp; Gas Inc.

3a. Address

816 North Street, Nacogdoches TX. 75763

3b. Phone No (include area code)

936-560-4747

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL &amp; 1650' FWL Section 6 17N 8W

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

## TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

9-22-11- RIH with WS to 1611.30, Mix & Pump 44 sks of Portland @ 15.0 ppg for bottom plug.

9-23-11- Tag bottom plug at 1272', pull WS to 600', mix & pump 80 sks @ 15.0 ppg for outside annulus plug. Mix & Pump 85 SkS @ 15.1 ppg for inside plug. Pull pipe, SD.

9-26-11- Tag plug at 153', Mix & pump 18 sks @ 15.0 ppg to top off well.

Cut off casing at 3', weld cap. Place Plug Marker. Clear location.

RCVD OCT 31 '11

OIL CONS. DIV.

DIST. 3

14 I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Mike Allen

Title Engineer

Signature

Electronic Submission

Date

10/10/2011

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title

Date

Office

OCT 26 2011

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

NMOC