

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-22028

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Steve Zink
Address PO Box 6459 Navajo Dam, NM 87419	Telephone No. 505-320-0677
Facility Name NEBU 7A	Facility Type Gas Well

Surface Owner BLM	Mineral Owner BLM	Lease No. SF 079060
-------------------	-------------------	---------------------

LOCATION OF RELEASE

Unit Letter I	Section 21	Township 30N	Range 7W	Feet from the 1,590'	North/South Line South	Feet from the 790'	East/West Line East	County Rio Arriba
------------------	---------------	-----------------	-------------	-------------------------	---------------------------	-----------------------	------------------------	----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Volume of Release UNK	Volume Recovered 169 Cu Yards Soil
Source of Release Below Grade Fiberglass Tank	Date and Hour of Occurrence Before 6/3/8 11:15 AM	Date and Hour of Discovery 6/3/8 11:15 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin	
By Whom? Steve Zink	Date and Hour 6/3/8 12:50 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD JUN 12 '08

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

A below grade double walled fiberglass tank was being replaced, after excavation discovered that tank had been leaking. This tank was replaced w/ a steel double walled below grade tank, after removing contaminated soils and replacing w/ new soil.

Describe Area Affected and Cleanup Action Taken.*

169 Cubic yards immediately around take area. Removed contaminated soils and took to Envirotech, replaced w/ new soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Zink	Approved by District Supervisor: 	
Title: Production Superintendent	Approval Date: 2/07/2012	Expiration Date:
E-mail Address: Steve.Zink@dmv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 9, 2008	Phone: 505-320-0677	

* Attach Additional Sheets If Necessary

nJK 1203842159