

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-28170

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Larry Schlotterback
Address 200 Energy Court	Telephone No. (505) 326-9425
Facility Name 500' North of Gallegos Canyon Unit 509	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No
---------------------------------	---------------	----------

LOCATION OF RELEASE

Unit Letter H	Section 28	Township 29N	Range 12W	Feet from the	LATITUDE	Feet from the	LONGITUDE	County San Juan
-------------------------	----------------------	------------------------	---------------------	---------------	----------	---------------	-----------	---------------------------

NATURE OF RELEASE

Type of Release: PRODUCED WATER	Volume of Release - 5 Barrels	Volume Recovered - N/A
Source of Release: Produced water transfer line	Date and Hour of Occurrence: May 22, 2008	Date and Hour of Discovery May 22, 2008
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD	
By Whom? Larry Schlotterback	Date and Hour: 5/22/08 - 3:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCUD JUN 3 '08

**OIL CONS. DIV.
DIST. 3**



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

At about 9:45 on May 22, 2008, an Enterprise Pipeline employee called BP about a water spill near Key Energy yard. Since Enterprise and BP have gas & water lines in the same area of the spill, BP shut in all adjacent wells to determine the source of the spill. It was determined after blowing down Enterprises' lateral that the spill was a BP waterline. From the measured area of wet soil, approximately 5 barrels of produced water spilled. A work order has been issued to repair the line (hydrovac) and remediate the spill area.

Describe Area Affected and Cleanup Action Taken.* Pipeline ROW soil impacted. The area will be allowed to dry and any salt stain will be removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry Schlotterback	Approved by District Supervisor: 	
Title: Field Environmental Coordinator	Approval Date: 2/07/2012 Expiration Date:	
E-mail Address: schlln@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/28//08 Phone: 505-326-9425		

* Attach Additional Sheets If Necessary

nJK1203829182

