

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-21968

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact Kristina Kovach	
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-326-9866	
Facility Name Sanchez A #2	Facility Type Gas Well	API # 30-039-21968
Surface Owner Federal	Mineral Owner Federal	Lease No. SF-079302A

LOCATION OF RELEASE



Unit Letter L	Section 20	Township T26N	Range R6W	Feet from the 1570'	North/South Line South	Feet from the 810'	East/West Line West	County Rio Arriba
-------------------------	----------------------	-------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.46872 ° N** Longitude **107.49755 ° W**

NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release - 5 BBL	Volume Recovered - 3 BBL
Source of Release: Tank leak	Date and Hour of Occurrence	Date and Hour of Discovery 3/15/08 - 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	RCVD APR 2 '08 OIL CON. DIV. DIST. 3
By Whom?	Date and Hour -	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A ConocoPhillips Company employee discovered a produced water spill of approximately 5 BBL at the Sanchez A #2 on the morning of 3/15/08. The release was caused by a small hole in a 120 BBL produced water tank, likely caused by corrosion. The hole was plugged upon discovery to stop the leak.		
Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids were contained within the berm, and approximately 3 BBL of spilled fluids were recovered by vacuum truck. The remaining fluids in the tank were pulled. A crew will attempt to repair the tank, but if the tank cannot be repaired, it will be replaced.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kristina L. Kovach	Approved by District Supervisor: 	
Title: Environmental Associate	Approval Date: 2/27/2012	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/24/08 Phone: 505-326-9866		

* Attach Additional Sheets If Necessary

nJK 1205837408