

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED**MAR 08 2012**

Sundry Notices and Reports on Wells

Farmington Field Office
Bureau of Land Management1. **Type of Well**
GAS5. **Lease Number**
NMSF-078197
6. **If Indian, All. or
Tribe Name**2. **Name of Operator****BURLINGTON****RESOURCES OIL & GAS COMPANY LP**7. **Unit Agreement Name**3. **Address & Phone No. of Operator**

PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. **Well Name & Number**
Feuille A 5E9. **API Well No.**

30-045-26249

4. **Location of Well, Footage, Sec., T, R, M**

Unit K (NESW), 1510' FSL & 1690' FWL, Section 4, T29N, R10W, NMPM

10. **Field and Pool**
Blanco MV / Basin DK11. **County and State**
San Juan, NM**12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA****Type of Submission****Type of Action**☐ Notice of Intent☐ Abandonment☐ Change of Plans☒ Other --☐ Plugback Dakota☒ Subsequent Report☐ Recompletion☐ New Construction☐ Plugging☐ Non-Routine Fracturing☐ Final Abandonment☐ Casing Repair☐ Water Shut off☐ Altering Casing☐ Conversion to Injection**13. Describe Proposed or Completed Operations**

2/22/2012 Notified BLM (Stephen Mason) & OCD (Brandon Powell) of plug change. Procedure calls for 12sx (35') on top of CIBP. Had to fish tbg and request permission to set 60' of cmt on top of CIBP. WOC & Tag. Verbal approval received.

The Dakota formation was plugback per the above notification and attached report. The subject well is now producing Blanco Mesaverde only.

RCVD MAR 14 '12

OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct.Signed Crystal Tafoya Crystal TafoyaTitle: Staff Regulatory TechnicianDate 3/8/2012

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ACCEPTED FOR RECORD**MAR 09 2012****FARMINGTON FIELD OFFICE****NMOCD**
A

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
Farmington, New Mexico 87499
505-325-2627 *fax: 505-325-1211

Burlington Resources
Feuille A #5E

February 27, 2012
Page 1 of 2

1510' FSL and 1690' FWL, Section 4, T-29-N, R-10-W
San Juan County, NM
Lease Number: SF-078197
API #30-045-26249

Plug and Abandonment Report
Notified NMOCD and BLM on 2/15/12

Plug and Abandonment Summary:

Plug #1 with CIBP at 6629' dump bail 5 sxs class C cement, from 6629' to 6557' to plug the Dakota interval.

Plugging Work Details:

- 2/16/12 Rode equipment to location. RU rig and equipment. SI well. SDFD.
- 2/17/12 Check well pressures: tubing 130#, casing 210# and bradenhead 0#. Blow well down. ND wellhead. NU mud cross. NU BOP and test. PU on tubing and attempt to pull tubing hanger; stuck. Pulled up to 50K; unable to work tubing free. RU Wireline Specialties. RIH and free point at 4042'. Tubing stuck at 4050'. Cut tubing at 4023'. Pump 16 bbls of 2% KCl water during cut. RD Wireline Specialties. TOH with 16 stands. SI well. SDFD.
- 2/20/12 Check well pressures: tubing 210#, casing 200# and bradenhead 10#. Blow down well. TOH and tally 103 joints 2-3/8" tubing with 1 18' cut off piece. TIH with 3-1/4" overshot and BHA; tag fish at 4022'. Worked pipe and jarred on fish. TOH with tubing and 14' fish. PU 4.5" string mill and RIH to 1863'. SI well. SDFD.
- 2/21/12 Check well pressures: casing and tubing 170# and bradenhead 0#. Blow well down. TIH with tubing and tag tight spot at 4040'. Determine to clean out with air. Wait on air package. Spot in Weatherford air package. RU with power swivel. Tag tight spot at 4040' and work clear to 4063'. Continue to work through tight spot. Fell through at 4099'. Pump 20 bbls of water down tubing to kill well. SI well. SDFD.
- 2/22/12 Check well pressures: tubing 180# and casing and bradenhead 0#. Blow well down. TIH with tubing and tag fill at 6569'. RU power swivel. Clean out with air to 6576'. Clean out to CIBP at 6629'. Circulate well clean. PUH above perforations. SI well. SDFD.
- 2/23/12 Check well pressures: tubing and casing 180# and bradenhead 0#. TIH and tag CIBP at 6629'; no fill. RU Tuboscope and inspect tubing while TOH. LD 27 bad joint. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
Farmington, New Mexico 87499
505-325-2627 *fax: 505-325-1211

Burlington Resources
Feuille A #5E

February 27, 2012
Page 2 of 2

1510' FSL and 1690' FWL, Section 4, T-29-N, R-10-W
San Juan County, NM
Lease Number: SF-078197
API #30-045-26249

Plug and Abandonment Report
Notified NMOCD and BLM on 2/15/12

Plug and Abandonment Summary:

- 2/24/12 Check well pressures: casing 180#, tubing and bradenhead 0#. Spot Plug #1. WOC. TIH and tag cement at 6557'. TIH with 2-3/8" expendable check, 2-3/8" F-nipple, 1 joint tubing, 1 2' sub, 152 joints, drift plus tally in. Land tubing at 4755'. ND BOP and mud cross. NU wellhead. RU air package. Pump 2 bbls of 2% KCl. Drop ball and pumped additional 2% KCl. Pressure test tubing to 1000#. Pop off expendable check at 1150#. SI well. SDFD.
- 2/27/12 Check well pressures: tubing 0#, casing 200# and bradenhead 0#. RU air package to casing. Blow well around and dry up well. RD rig and equipment. RD equipment. Move off location.

Derrick McCuller, BLM representative, was on location.
Jimmy Morris, MVCI representative, was on location.