# RECEIVED

submitted in lieu of Form 3160-5

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAR 12 2012

Farmington Field Office

Bureau of Land Managemen. Sundry Notices and Reports on Wells 5. Lease Number NMSF-078438 Type of Well 6. If Indian, All. or Tribe Name GAS 7. **Unit Agreement Name** San Juan 32-9 Unit Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY LP 8. Well Name & Number San Juan 32-9 Unit 257S Address & Phone No. of Operator 9. PO Box 4289, Farmington, NM 87499 (505) 326-9700 API Well No. 30-045-32525 Location of Well, Footage, Sec., T, R, M 10. Field and Pool Unit F (SENW), 1415' FNL & 1635' FWL, Section 8, T31N, R9W, NMPM **Basin Fruitland Coal** 11. **County and State** San Juan, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action X Notice of Intent Abandonment Change of Plans **New Construction** Recompletion Plugging Non-Routine Fracturing Subsequent Report Water Shut off Casing Repair Conversion to Injection Final Abandonment Altering Casing 13. Describe Proposed or Completed Operations Burlington Resoures requests permission to P&A the subject well per the attached procedure, current and proposed wellbore schematics. RCVD MAR 19'12 Notify NMOCD 24 hrs OIL CONS. DIV. prior to beginning DIST. 3 operations 14. I hereby certify that the foregoing is true and correct. Title Staff Regulatory Technician Date 3 Signed Dollie L. Busse (This space for Federal or State Office use) MAR 1 3 2012 APPROVED BY \_Original Signed: Stephen Mason \_Title \_ Date

Title 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

CONDITION OF APPROVAL, if any:

### ConocoPhillips SAN JUAN 32-9 UNIT 257S Expense - P&A

Lat 36° 54' 56.988" N

Long 107° 48' 20.988" W

#### **PROCEDURE**

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5. TOOH with rod string. LD rod string. ND wellhead and NU BOPE. Function test BOP. PU and remove tubing hanger. TOOH with tubing string.

Rods:	Yes	Size:	3/4"	Length:	3512'
Tubing:	Yes	Size:	2-3/8"	Length:	3539'
Packer:	No	Size:	NA	Depth:	NA

Modify the work sequence as appropriate due to rods in the hole.

- 6. Round trip casing scraper to 3270' or as deep as possible (whichever is shallower).
- 7. RIH and set 7" CR at 3263'. Load hole. Pressure test tubing to 1000 PSI. Pressure test casing to 800 psi. If casing does not test, spot and tag subsequent plug as necessary.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

8. Plug 1 (Fruitland Coal Open Hole & Formation Top, 3078-3263', 46 Sacks Class B Cement)

Mix 47 sxs of Class B cement and spot a balanced plug to cover the Fruitland coal open hole & formation top. PUH.

9. Plug 2 (Kirtland and Ojo Alamo Formation Top, 1883-2088', 50 Sacks Class B Cement)

Mix 50 sxs of Class B cement and spot a balanced plug to cover the Kirtland & Ojo Alamo formation tops. PUH.

10. Plug 3 (Nacimiento Formation Top, 720-820', 29 Sacks Class B Cement)


Mix 29 sxs of Class B cement and spot a balanced plug to cover the Nacimiento formation tops. POOH.

### 11. Plug 4 (Surface Shoe, 0-195', 48 Sacks Class B Cement)

Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 psi; note the volume to load. If the BH annulus holds pressure then establish circulation out casing valve with water. Mix 48 sxs Class B cement and spot balanced plug inside casing from 195' to surface, circulate good cement out casing valve. TOH and LD tubing.

Shut in well and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the 7" casing and the BH annulus to surface. Shut well in and WOC.

12. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.



onoco eli Nă w	在一个一个一个人的人们的特殊的数据,这个人是这种的	Propos 75	
532525	NMPM_008-031N-009VV   Res	IN (FRUITLAND COAL)	NEW MEXICO
6,704.0		IB-Giorid Distailer	(67.16.00) (97.16.00) (97.16.00)
. 4	The second of th	Well Config	- Original Hole, 1/1/2020
FI.	P CHANGE	Schematic - A	Ordinal Superior State
»   · ·		Scrientauc - A	Actual Frm Final
! <u> </u>			
ا ابنا	minini vieni v	<del></del>	Anthum com a commentation and the comment
4			
۰	face, 9 5/8in, 9.001in, 12 ftKB, 445 ftKB		Cemented with 110 sxs Type III cement.
1			Ctroutated 0 bble to ourface.   Plug #4, 12-195, 1/1/2020, Mix 48 sxs Class
i2  5			B coment and spot balanced plug inside
0		Derron D	casing from 195' to surface, circulate good cement out casing valve.
0 -			Plug #3, 720-820, 1/1/2020, Mix 29 sxs of NACIMIENTO, 73
0	• • • • •	8A	Class B cement and spot a balanced plug to cover the Nacimiento formation tops.
83   33			
38 —			Plug #2, 1,000-2,000, 1/1/2020, Mix 50 3x3 of KRTLAND, 2,00
88			Class B cement and spot a belanced plug to cover the Kirtland & Oto Alamo formation
78 -			tops.
28			Plug #1, 3,078-3,263, 1/1/2020, Mix 47 sxs of FRUITLAND, 3,1 Class B centeral end sput a balanced plug to
63 64	Cement Retainer, 3,263-3,264		cover the Fruitiand Coal open hole &
69			formation top.
70			<b>]</b>
92			
99   ··· 12		01 10	1
13	Intermediate1, 7in, 6.456in, 12		SINGLE STAGE, 12-3,313, 11/11/2004, Cemented with 507 sxs Type III cement.
15 -	(IKB, 3,313 (IKB	]	Circulated 50 bbis to surface.
63 · ··			
64	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
∩7   28			
48		į į	
71		i i	
14		l t.	
23 ··· 24		1 1	· · · · · · · · · · · · · · · · · · ·
25	,		
20 -		1 l	PICTURED CLIFF 3,528
35			3,528
20 -		<u> </u>	
40			
45 51	PBTD, 3,558	ľ	
57	Production1, 5 1/2in, 4.950in, 3,299 ftKB, 3,558 ftKB		
58	TD, 3,558, 12/8/2004	<del></del>	<b>≒</b>

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 257S San Juan 32-9 Unit

## **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Bring the top of the Fruitland plug to 3061'.
- b) Place the Kirtland/Ojo Alamo plug from 2191' 2034'.
- c) Place the Nacimiento plug from 658' 558'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.: