

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-23586

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Benson-Montin-Greer Drilling Corp.	Contact Mike Dimond
Address 4900 College Blvd	Telephone No. 505-325-8874
Facility Name Homestead Ranch #2	Facility Type Producing Well

Surface Owner Various Private	Mineral Owner Various Private	Lease No. Fee
-------------------------------	-------------------------------	---------------

LOCATION OF RELEASE

Unit Letter N	Section 34	Township 25N	Range 2W	Feet from the 990	North/South Line South	Feet from the 1850	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	-------------	----------------------	---------------------------	-----------------------	------------------------	----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 85 Bbls	Volume Recovered 5
Source of Release Sales Tank #40385 on location	Date and Hour of Occurrence Early Morning of January 8, 2008	Date and Hour of Discovery 9:00 am January 8, 2008
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RCVD FEB 26 '08
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

BS&W valve on tank froze and split causing spray of high gravity crude and produced water. Vacuumed approximately 5 bbls of pooled oil inside berm and transferred remaining liquid in tank #40385 to tank #40384

Describe Area Affected and Cleanup Action Taken.*

Affected area all inside bermed area of tank battery. Area covered with snow and could not see evidence of contamination. Waiting on drier conditions to geoprobe site and discover depth of any contamination.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Mike Dimond	Approved by District Supervisor: 	
Title: President	Approval Date: 2/27/2012	Expiration Date:
E-mail Address: mikedimond@bmgdrilling.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/25/2008	Phone: 505-324-5069	

* Attach Additional Sheets If Necessary