RECEIVED

Form 3160-5 (February 2005)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

JUN 12 2012

FORM APPROVED OMB No 1004-0137 Expires March 31, 2007

Farmington Field Offices. Lease Serial No							
SUNDRY NOTICES AND REPORTS ON WELL Sof Land Manage Do not use this form for proposals to drill or to re-enter an					6 If Indian, Allottee or Tribe Name		
abandoned well. Use Form 3160-3 (APD) for such proposals.							
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7 If Unit of CA/Agreement, Name and/or No. Rosa Unit		
1 Type of Well					Rosa Offic		
Oıl Well Gas Well Other					8 Well Name and No Rosa Unit #209A		
2. Name of Operator					9. API Well No.		
WPX Energy Production, LLC 3a Address 3b Phone No (include area code)					30-039-27699		
PO Box 640 Aztec, NM 87410 505-333-1808				=)	10 Field and Pool or Exploratory Area Basin Fruitland Coal		
4 Location of Well (Footage, Sec., T., R, M, or Survey Description) SHL 1087' FSL & 976' FEL BHL 144' FSL & 1' FWL, sec 24, T31N, R6W					11 Country or Parish, State Rio Arriba		
12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
	Acidize Deepen Production (S			Production (Sta	art/Resume) Water Shut-Off		
Notice of Intent	Alter Casing Fracture Treat			Reclamation		Well Integrity	
	Casing Repair	New Construct					
Subsequent Report	Change Plans		Plug and Abandon Temporarily Abandon				
Final Abandonment Notice	Convert to Plug Back Water Disp				al		
duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)							
4/25/12- MIRU HWS #12 FOR SIDETRACK PREP SET RTBP @ 2650'						RCVD JUN 15'12	
4/26/12- RDMO LOCATION						OTL CONS. DIV.	
<u>5/8/12</u> - MIRU AWS #980						DS T.3	
5/9/12- INSTALL TEST PLUG & PRESS TEST PIPE & BLIND RAMS, CHOKE MAN VALVES, CHOKE & KILL LINE VALVES @ 250 LOW 5 MIN EACH, #1500 HIG 10 MIN EACH. PLUG TEST PUMP & CHARTS VALVES FAILED							
5/10/12- PULL TEST PLUG & PRESS TEST 7" CSG AGAINST BLINDS @ #1500 FOR 30 MIN, ALL TEST GOOD. PRESSURE TEST VALVES @ #250 LOW 5 MIN EACH, #1500 HIGH 10 MIN EACH, ALL TEST GOOD.							
14 I hereby certify that the foregon Name (Printed/Typed)	ng is true and correct						
Larry Higgins				Title Permit Supervisor			
Signature Date 6/12/12							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by							
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction							

5/11/12-5/12/12-RIH AND SET WHIPSTOCK MILL WINDOW IN 7" CSG FROM 2623' TO 2636'

5/13/12-5/14/12- DRILL 6-1/4" CURVE, 2636'-3520'

5/14/12-5/19/12- DRILL 6-1/4" LATERAL, 3520'- 6557' TD 6-1/4" LATERAL @ 6557' (TVD @ 3143')
RUN 83 JTS, 4-1/2", 11.6 #, J-55, LT&C PERFORATED CASING (28, 0 50" HOLES P/FT) AND 12 JTS 4-1/2", 11.6 #, H-55, LT&C NON-PERFORATED CASING SET @ 6550', TOL @ 2640'. TOP PERF SET @ 3192', BOTTOM PERF SET @ 6547'

5/20/12 - RDMO AWS # 980 '

5/22/12- MIRU HWS #12 TO C/O LATERAL, RUN RODS AND LAND TUBING

5/23/12-6/5/1212- C/O LATERAL

6/6/12- POOH WITH WHIPSTOCK

6/7/12- RETRIEVE RBP @ 2650', LAND PRODUCTION TBG 2 7/8", 98 JTS TOTAL, EUE 8RD J-55 6 5# AS FOLLOWS TOP DOWN TBG HANGER 1 JT, 10'TBG SUB, 96 JTS ,SN,1 JT MA WITH 1/2 MULE SHOE SN@3136' EOT@ 3169' WITH 2460' OF 1/4" CHEM CAP BANDED TO OUTSIDE OF 2 7/8" TBG

6/10/12- RUN PUMP AND RODS AS FOLLOWS 1-1/4"X26" PLOISHED ROD WITH 1-1/2"X16" LINER, 1-6' PONY ROD, 121 3/"X25' RODS, 3-1 3/" SINKER BARS, 2 1/2"X2"X24' RWAC SAND PRO HBR PUMP.

