## Form 3160-5 (March 2012)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED

FORM APPROVED OMB No 1004-0137 Expires: October 31, 2014

MAY 30 2012 5. Lease Serial No.

NMSF078	318-A		
IfIndian	Allottee	Triba Name	

SUNDRY NOTICES AND REPORTS ON WELLShington Field ., 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter and Management.

abandoned well. Use Form 3160-3 (APD) for such proposals 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other USA 23 #1 2. Name of Operator Chevron USA Onc. 9. API Well No. 30-045-31110 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area ATTN: Regulatory Specialist 332 Road 3100 Aztec New Mexico 87410 71629 Basin Fruitland Coal (Gas) 505-333-1941 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 390 FSL 627 FEL S 23 -T32N -R13W San Juan, New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) ✓ Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Other Change pump, clean Casing Repair New Construction Recomplete Subsequent Report out, inspect tubing Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Approximate start date 7/1/2012 1. Remove downhole rods, pump and tubing. 2. Tag for fill and cleanout to PBTD @ 1893'. RCVD JUN 7'12 3. Run production tubing and land at ~1810'. Run rods and new 2" tubing pump with retrievable standing valve. OIL CONS. DIV. 5. Install Lufkin 228-213-86 pumping unit. Notify NMOCD 24 hrs prior to beginning DIST. 3 See attached current wellbore schematic operations

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)			
April E. Pohl	Title Regulatory Specialist		
Signature Adil & Pohl	Date 05-29-2012		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by	Title Detr. Eac Date 6/4/12		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or c that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon.	ertify		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



## **USA 23-1**

San Juan County, New Mexico Sec 23 – T 32N – R 13W Field: Basin

API: 30-045-31110

- 1. REMOVE DOWNHOLE RODS. PUMP AND TUBING.
- 2. TAG FOR FILL AND CLEANOUT TO PBTD @ 1893'.
- 3. Run production tubing and land at  $\sim 1810$ '.
- 4. Run rods and new 2" tubing pump with retrievable standing valve.
- 5. Install Lufkin 228-213-86 pumping unit.

## See Current Wellbore Diagram:

