RECEIVED

Form 3160-5 (August 2007) UNITED STATES JUN 21 2012

DEPARTMENT OF THE INTERIOR

OMB No. 1004-0137 Expires: July 31, 2010

FORM APPROVED

	BUREAU OF LAND MA	NAGEMENIngton Field	1 0#4	Expires July 31, 2010
		Bureau of Land Ma	nagemen.	NM-02874-A
Do not us	NDRY NOTICES AND REP e this form for proposals I well. Use Form 3160-3 (A	ORTS ON WELLS to drill or to re-enter a	6 If Indian, Allottee o	
S	UBMIT IN TRIPLICATE - Other in	structions on page 2	7. If Unit of CA/Agre	ement, Name and/or No
1. Type of Well				Huerfano Unit
Oil Well	X Gas Well Other		8 Well Name and No	Huerfano Unit 177R
2 Name of Operator			9 API Well No	00.045.04000
3a Address	iton Resources Oil & Gas		ode) 10 Field and Pool or	
PO Box 4289, Farming	on, NM 87499	(505) 326-9700		Basin Dakota
Burlington Resources Oil & Gas Company LP 30-045-24299 10 Field and Pool or Exploratory Area Basin Dakota 11 Country or Parish, State San Juan New Mexico 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent				
12. CHECK	THE APPROPRIATE BOX(ES) TO INDICATE NATURE	OF NOTICE, REPORT O	R OTHER DATA
TYPE OF SUBMISSION		TYPE	OF ACTION	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
BP		Plug and Abandon	X Temporarily Abandon	Plugback DK
Final Abandonment Notice	<u> </u>			
Burlington Resources	requests permission to pl itial per the attached proc	edure, current and pro	-	•
	·	No I	prior to beginning	OIL COMS. DIV.
# Notify NMOCD	24 hrs prior to pre	essure testing		
14 I hereby certify that the foregoing is	true and correct. Name (Printed/Typ	ped)		
Dollie L. Busse		Title Staff I	Regulatory Technician	
Signature Willia	1 Busse	Date 6/	121/12	
	THIS SPACE FO	OR FEDERAL OR STAT	TE OFFICE USE	
Approved by Original Si	gned: Stephen Mason	Tı	tle	Date JUN 2 5 2017
Conditions of approval, if any, are attact that the applicant holds legal or equitabentitle the applicant to conduct operation	le title to those rights in the subject leans thereon.	ase which would Of	ffice	
Title 18 U S C Section 1001 and Title	43 U.S C Section 1212, make it a crim	ne for any person knowingly and	willfully to make to any departm	ent or agency of the United States any

MMOCD

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ABANDONMENT PROCEDURE

June 8, 2012

Huerfano Unit 177R (DK)

Basin Dakota 900' FSL & 1640' FEL, Spot O, Section 22 -T 026N - R 010W San Juan County, New Mexico / API 3004524299 Lat 36° 28' 7.388" N / Long 107° 52' 46.776" W

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- 1. This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- 2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function and pressure test BOP. PU and remove tubing hanger. TOOH with tubing.

3.	Rods: Yes,	No <u>X</u> ,	Unknown	_•		
	Tubing: Yes_X_,	No,	Unknown	_Size2 <u>3</u>	<u>/8"</u> , Set Depth	6614'
	Packer: Yes,	No <u>X</u> ,	Unknown	_Type	·	

- 4. Plug #1 (Dakota perforations & Dakota formation top, 6594 6494'): RIH and set CR at 6594'. Pressure test casing to 800 psi. If casing does not test, isolate leaks and contact production engineer with results. Load casing with water and attempt to establish circulation. Mix 12 sx Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top.
- 5. Circulate well clean with water. Pressure test (MIT) casing to 560 psi for 30 min and record on a 2-hour chart with a 1000# spring. (NMOCD requires a 30 min. test, no more than 10% pressure loss, and rate must be stabilized). If casing does not test, Call Area 21 engineer (Sylvia Andrus 326 9532) to further instructions.
- 7. Pump corrosion inhibiting fluid ("packer fluid") until water is displaced. Contact Jerah Taylor (505-330-5794) at NALCO for treatment details. TOOH and LD tubing. Add additional packer fluid as necessary.
- 8. ND BOPE & NU wellhead. RDMO.

1,311 -	Trace Land	HUERFANO UNITERFAR							
Scrientic Advantage Adva	04524299	NMPM,022-026N-010W	ASIN DURCHA	(CAD UBTRACED.		NEW MEXICO)		
Scheinetic - Actuel Surface Cesting Cement, 12-218, 10M/1980,			KE	Gondosaice L	w 200	Record digital de Organo	3 (A) (D)=1	(ppid)HäiderDistarcs((D)
Schemetic - Actual Surface Casing Cement, 12-218, 104/1990, CEMENT WITH 16S CU FT CRCULATED TO Surface, 6 5/6lin, 8 0/97lin, 12 ft/KB, 216 ft/KB COJO ALAMO, KIRTLAND, FRUITLAND, FRUITLAND, Casing cement, 2,000-2,276, 10/16/1989, CASING cement, 2,000-2,100, CAS	A COLUMN TO A COLUMN TO THE CO	TO TENTO THE LEGISLES TO STREET OF THE THE PARTY OF THE P	₩e	II Config.	Original Hole	1/1/2020		12" 1 . W. J. V.	رُوْع ک
Surface Cesting Cement, 12.218, 109/1980,	TRAFFIC A SPECIAL CONTRACTOR			Schematic -	ctual		organista († 1854) 1886 - Nobel Stanton, samt († 1888)	Frm Fin€	al o
Surface Leasing Cement, 2000-2,278, 10/18/1980									
Surface, 6 5/6in, 6.097in, 12 ftkB, 216 ftkB								** ***** ***	
					/ SURFA	CE		**	
KIRTLAND, FRUITAND, FRUI					Surface	a, 8 <i>5/</i> 8in, 8.097in, 12	ftKB, 218 ftKB	2 tg 2 10 1 10 10 10 10 10 10 10 10 10 10 10 1	
PICTURED CI 2,092 274 Casing cement, 2,000-2,276, 10/18/1980, CEMENT WITH 454 CU FT TOC DETERMINED BY TEMP SURVEY CHACRA, 2 Casing cement, 3,206-5,101,107/8/1980, CEMENT WITH 455 CU FT TOC CALC AT 75% EFF Casing cement, 3,206-5,101,107/8/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF Casing cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. Cement Retainer, 6,594-6,595 Cement Retaine	127		-					OJO ALAMO,	1,127
DOI	311		7					KIRTLAND, 1	i <mark>,311</mark> -
PICTURED CI	,810		- 1			Managed Association (Association Control of the Association Control of the		FRUITLAND,	1,810
2,092 2774 2776 2776 2776 2776 2776 2776 277	,000							DIOTUSES S	
Casing cement, 2,000-2,276, 1078/1980, CEMENT WITH 464 CUFT TOC DETERMINED BY TEMP SURVEY CHACRA, 2 PONT LOOKOL CEMENT WITH 55S CUFT TOC CALC AT 75% EFF GALLUP, 5 GREENHORN, GREENHORN, GREENHORN, CHACRA, 2 CHACRA, 2 CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. CHACRA, 2 PULIS #1, 6,494-6,594, 17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. PERF DAKOTA, 6,844-6,860, 11/9/1980]	092								JEF 5,
Casing cement, 3,208-5,101, 10787980, FRAC DAKOTA, 6,594-6,595 Cement Retainer, 6,594-6,5	274				Casing	cement, 2.000-2 276	10/18/1980		
208 6855	276			1231	CEMEN.	T WITH 464 CU FT TO			
MESA VERDE MESA VERDE MENEFEE, 3 MESA VERDE MENEFEE, 3 POINT LOOKOL Gasing cement, 3,208-5,101,10/18/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF GALLUP, 5 GREENHORN, GREENHORN, GREENHORN, GREENHORN, GREENHORN, GREENHORN, Hydraulic Fracture, 11/6/1980, FRAC DAKOTA WITH 51700# FRAC DAKOTA WITH 51700# FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER BSO Production Casing Cement, 5,540-6,887, Production Casing Cement, 5,540-6,887, Production Casing Cement, 5,540-6,887, Production Casing Cement, 5,540-6,887,	,980		\dashv [EX IEW	IP SURVEY		CHACRA, 2	,980
691 490 099 101 Casing cement, 3,208-5,101,10/18/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF GALLUP, 5 680 GRANEROS, 682 Cement Retainer, 6,594-6,595 Cement Retainer, 6,594-6,595 GRANEROS, 684 Hydraulic Fracture, 11/8/1980, FRAC DAKOTA WITH 51700# 680 SAND AND 44500 GAL WATER 680 PDITE 6,850 PROVIDENCE OF TOC CALC AT 75% EFF Casing cement, 3,208-5,101,10/18/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF GRANEROS, GRANEROS, Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 644 PERF DAKOTA, 6,644-6,680, 11/8/1980 POINT LOOKOL DAKOTA, 6 PERF DAKOTA, 5,644-6,680, 11/8/1980 POINT LOOKOL PERF DAKOTA, 10/18/1980 PERF DAKOTA, 5,644-6,680, 11/8/1980 POINT LOOKOL PROVIDENCE OF TOC CALC AT 75% EFF PROVI	,208			22 0				,	
Casing cement, 3,208-5,101, 10#8/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF	655		-1/2					- MESA VERDE,	, 3,555
Casing cement, 3,208-5,101,10/18/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF GALLUP, 5 GRANEROS, 650 Plug #1, 6,494-6,594,17/2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# SAND AND 44600 GAL WATER FROM DAKOTA, 6 PERF DAKOTA, 6,644-6,680, 11/9/1980 Production Casing Cement, 5,540-6,687, Production Casing Cement, 5,540-6,687,	691							MENEFEE, 3	1,691 -
Casing cement, 3,208-5,101, 1018/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF GALLUP, 5 GREENHORN, 483 GREENHORN, GREENHORN, 680 Cement Retainer, 6,594-6,595 Cement Retainer, 6,594-6,595 Cement Retainer, 6,594-6,595 Application Casing Cement, 3,208-5,101, 1018/1980, CEMENT WITH 555 CU FT TOC CALC AT 75% EFF GALLUP, 5 GRANEROS, GREENHORN, GRANEROS, Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 PERF DAKOTA, 6,644-6,680, 11/9/1980 FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER FPBTD, 6,650 Production Casing Cement, 5,540-6,867, Production Casing Cement, 5,540-6,867,	490							POINT LOOKOU	IT, 4,49
CEMENT WITH 5SS CU FT TOC CALC AT 75% EFF GALLUP, 5 GREENHORN, GREENHORN, GREENHORN, GREENHORN, GREENHORN, GREENHORN, GRANEROS, S82 Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER FROM DAKOTA, 6,644-6,680, 11/9/1980 SAND AND 44600 GAL-WATER Production Casing Cement, 5,540-6,867, Production Casing Cement, 5,540-6,867,	,099	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					40404000 1	, , ,	•
GALLUP, 5 GALLUP, 5 GRENHORN, 494 537 582 Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. Cement Retainer, 6,594-6,595 DAKOTA, 6 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER Perf DAKOTA, 6,644-6,680, 11/9/1980 Production Casing Cement, 5,540-6,867,	,101							a weather o	, , , .
GREENHORN, 494 537 582 583 594 Cement Retainer, 6,594-6,595 Cement Retainer, 6,594-6,595 Application top. PERF DAKOTA, 6,644-6,680, 11/9/1980 SAND AND 44600 GAL-WATER Perf DAKOTA, 6,644-6,680, 11/9/1980 Production Casing Cement, 5,540-6,867, Production Casing Cement, 5,540-6,867,	540			72.0	EFF				
GREENHORN, 494 537 582 583 594 Cement Retainer, 6,594-6,595 Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. 614 640 644 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA, WITH 51700# 680 SAND AND 44600 GAL-WATER 650 Performation Casing Cement, 5,540-6,667, Production Casing Cement, 5,540-6,667,	,650				·			GALLUP, 5,	,650
494 537 582 583 594 Cement Retainer, 6,594-6,595 Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. 640 640 644 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# 680 SAND AND 44600 GAL-WATER 850 PETD, 6,850 PRID, 6,850 Production Casing Cement, 5,540-6,867,	483					A			
GRANEROS, 582 583 594 Cement Retainer, 6,594-6,595 Cement Retainer, 6,594-6,595 Above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER Production Casing Cement, 5,540-6,867, Production Casing Cement, 5,540-6,867,					hat e e		- 1 = 11 - 1 - 1		
582 583 594 Cement Retainer, 6,594-6,595 Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 644 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER Perf DAKOTA, 6,644-6,680, 11/9/1980 Perf DAKOTA, 6,644-6,680, 11/9/1980 Production Casing Cement, 5,540-6,867,			_8				1.1980 - 1.194	— GRANEROS.	6,537
Plug #1, 6,494-6,594, 1 <i>M</i> /2020, Mix 12 sxs Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER Perf DAKOTA, 6,644-6,680, 11/9/1980 Production Casing Cement, 5,540-6,867,									•
Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. Class B cement and spot inside the casing above CR to isolate the Dakota perforations and formation top. DAKOTA, 6 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# SAND AND 44600 GAL-WATER Perf DAKOTA, 6,644-6,680, 11/9/1980 Production Casing Cement, 5,540-6,867,						6 494 6 594 4 M MOS	00 Miy 12 ava].		
595 and formation top. 614 640 Application Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# 680 SAND AND 44600 GAL-WATER 680 PBTD, 6,850 Production Casing Cement, 5,540-6,867,	594				Class B	cement and spot insi	de the casing	No facility and all the safe of	. <i></i>
640 640 644 Hydraulic Fracture, 11/9/1980, FRAC DAKOTA WITH 51700# FRAC DAKOTA WITH 51700# PERF DAKOTA, 6,644-6,680, 11/9/1980 PRODUCTION Casing Cement, 5,540-6,867, Production Casing Cement, 5,540-6,867,	Cemen	t Retainer, 6,594-6,595					ta perforations		
640 644									
644 . Hydraulic Fracture, 11/9/1980,								DAKOTA P	E40
FRAC DAKOTA WITH 51700# PERF DAKOTA, 6,644-6,680, 11/9/1980 SAND AND 44600 GAL-WATER Production Casing Cement, 5,540-6,867,	· ·	lic Fracture 11/9/1980						DANUTA, b	,040 —
850 PPDTD, 6.850 Production Casing Cement, 5,540-6,867,	FRAC	DAKOTA WITH 51700#			PERF D	AKOTA, 6,644-6,680,	11/9/1980		
					Product	tion Casing Cament 5	540-6 867		
		PBTD, 6,850]			/10M8M	980, CEMENT WITH 38		* "" " " " " " " " " " " " " " " " " "	
866 / CALC AT 75% EFF / Production1, 4 1/2in, 4.052in, 12 ftKB, 6,867 / ftKB	1	[TO 0 007 10404075]					12 ftKB. 6.867	44 N 74 74 M 75 N 77 N 78 N 78 N 78 N 78 N	