

RECEIVED

JUL 11 2012

Farmington Field Office
Bureau of Land ManagementUNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

SUDDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1 Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2 Name of Operator

Burlington Resources Oil & Gas Company LP

3a. Address

PO Box 4289, Farmington, NM 87499

3b Phone No. (include area code)

(505) 326-9700

4. Location of Well (Footage, Sec., T, R, M., or Survey Description)

Surface UNIT H (SENE), 1840' FNL & 1160' FEL, Sec. 3, T26N, R10W

5 Lease Serial No

SF-078267A

6 If Indian, Allottee or Tribe Name

7 If Unit of CA/Agreement, Name and/or No

Huerfano Unit

8 Well Name and No

Huerfano Unit 110E

9 API Well No

30-045-26278

10. Field and Pool or Exploratory Area

Basin Dakota

11 Country or Parish, State

San Juan, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☒ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13 Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

6/20/12 MIRU AWS 731. ND WH. NU BOPE. PT BOPE. TEST OK. 6/22/12 TOO H w/ tbg. TIH w/ CIBP @ 6,748'
6/25/12 Perform MIT. PT to 500#/30 min. Test OK. Chart Attached. PT casing to 600#/30 min. Test OK.
ND WH. NU BOPE. RD RR @ 13:00 hrs on 6/26/12.

RCVD JUL 18 '12
OIL CONS. DIV.
DIST. 3

NMOCD T/A EXPIRES 6-25-17
FEDERAL EXPIRATION MAY VARY
CONTACT BLM FOR FEDERAL
EXPIRATION DATE

14 I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

DENISE JOURNEY

Title

REGULATORY TECHNICIAN

Signature

Denise Journey

Date

7/6/2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

JUL 16 2012

FARMINGTON FIELD OFFICE

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCD

JL




CHART NO.

HTR

METER

6000

AWS 721

CHART PUT ON



2.25.12

LOCATION

Hverfanga

REMARKS

VASS

TAKEN OFF

30 MIN. ALT. TEST
6000 PSI