

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

AUG 21 2012

FORM APPROVED
OMB No 1004-0137
Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
Jicarilla Contract 108
6. Indian, Allottee or Tribe Name
Jicarilla Apache Tribe

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
EnerVest Operating, L.L.C.

3a. Address
1001 Fannin St Ste 800 Houston, Texas 77002

3b. Phone No. (include area code)
713-495-6530

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
150' FSL & 275' FWL of UL M, Sec 14, T 26N, R 05W

7. If Unit of CA/Agreement, Name and/or No

8. Well Name and No
Jicarilla C #2M

9. API Well No.
30-039-29927

10. Field and Pool or Exploratory Area
Blanco Mesaverde/Basin Dakota

11. County or Parish, State
Rio Arriba

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Spud to Surf Csg
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

7-11-12 Notified BLM and OCD of Spud and csg & cmt work @ 4:45 p.m.;
Spud well at 02:00 7-12; Drill 12 1/4" hole to 64';
7-12-12 Drill 12 1/4" hole to 517'; WLS @ 150' 0.75 deg, 484' @ 1.50 deg;
Ran 9 5/8" 36# J-55 csg to 515'; Cmt w/ 225 Sx Type III 1.39 yield;
Rod Velarde was present for cement work;
Good cmt returned to surface; WOC;

RCVD AUG 27 '12
OIL CONS. DIV.
DIST. 3

ACCEPTED FOR RECORD

AUG 23 2012

FARMINGTON FIELD OFFICE
BY TL Salvors

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Ronnie L. Young

Title Regulatory Manager

Signature

Date

8.12.12

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

NMOCD W