RECEIVED

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR 10 2012 BUREAU OF LAND MANAGEMENT 10 2012

FORM APPROVED OMB No. 1004-0137 Expires. July 31, 2010

		Formington Field Og	5 Lease Serial No		
		Farmington Field Office	SI SI	F-080379-A	
		Bureau of and Manager	If Indian, Allottee or Tribe	Name	
	e this form for proposals t well. Use Form 3160-3 (A				
SUBMIT IN TRIPLICATE - Other instructions on page 2			7 If Unit of CA/Agreement, Name and/or No.		
1 Type of Well Oil Well Other Other			San Juan 29-6 Unit		
			8 Well Name and No		
			San Juan 29-6 Unit 246 9. API Well No.		
2 Name of Operator ConocoPhillips Company			1	039-24824	
3a Address 3b Phone No (include			· · · · · · · · · · · · · · · · · · ·		
PO Box 4289, Farmington, NM 87499		(505) 326-9700	Basin	Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit K (NESW), 1513' FSL & 1990'		FWL, Sec. 8, T29N, R6W	11. Country or Parish, State Rio Arriba	, New Mexico	
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	OTICE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION		TYPE OF A	CTION		
Notice of Intent	Acidıze	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
BP 1	Change Plans	X Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
determined that the site is ready for		only after all requirements, including rec	RC	VD AUG 14'12 IL CONS. DIV. DIST. 3	
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Typ	ed)			
Dollie L. Busse		Title Staff Regula	Title Staff Regulatory Technician		
Signature	: A Besse	Date 8/10	1/12		
THIS SPACE FOR FEDERAL OR STATE OF			FICE USE	EPTED FOR RECORD	
Approved by		Title		AUG 1 3 2012	
Conditions of approval, if any, are attach	= =	warrant or certify	FARK	NGTON FIELD-OFFICE	
that the applicant holds legal or equitabl	e title to those rights in the subject lea	ase which would Office	Fig.	20-	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

entitle the applicant to conduct operations thereon

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Conoco Phillips
San Juan 29-6 Unit #246

July 12, 2012 Page 1 of 1

1513' FSL and 1990' FWL, Section 8, T-29-N, R-6-W Rio Arriba County, NM Lease Number: SF-080379-A API #30-039-24824

Plug and Abandonment Report Notified NMOCD and BLM on 7/9/12

Plug and Abandonment Summary:

- **Plug #1** with 30 sxs (35.4 cf) Class B cement inside casing from 3377' to 3217' to cover the Fruitland Coal and Fruitland top.
- Plug #2 with 70 sxs (82.6 cf) Class B cement inside casing from 2962' to 2589' to cover the Kirtland and Ojo Alamo tops.
- Plug #3 with 29 sxs (34.22 cf) Class B cement inside casing from 1461' to 1307' to cover the Nacimiento top.
- Plug #4 pump 127 sxs (149.86 cf) Class B cement 72 sxs (84.96 cf) in 7" casing, 55sxs (64.9 cf) in annulus from 380' to surface.
- Plug #5 spot 15 sxs Class B cement; top off casing and annulus and install P&A marker.

Plugging Work Details:

- 7/10/12 MOL. RU rig and perform LO/TO. Check well pressures: casing 90 PSI, tubing 90 PSI and bradenhead 0 PSI. RU relief lines and blow well down. ND wellhead. NU BOP and pressure test. TOH and tally 53 stands 2-3/8" tubing with F-nipple and pop off valve, 3629'. Round trip 7" string mill to 3408'. SI well. SDFD.
- 7/11/12 Check well pressures: no tubing, casing 85 PSI and bradenhead 0 PSI. TIH with 7" DHS CR and set at 3377'. Pressure test tubing to 1000 PSI. Establish circulation and pressure test casing to 800 PSI. Spot plug #1. Establish circulation. Spot plug #2. Establish circulation. Spot plug #3. TOH with tubing. Perforate 3 HSC holes at 100'. Establish circulation out annulus. TIH with tubing to 380'. Establish circulation. Spot plug #4. TOH and LD tubing. SI well. SDFD.
- 7/12/12 Open up well; no pressures. ND BOP. Perform and write Hot Work permit. Cut off wellhead. Found cement down 2' in casing. Spot plug #5. Install P&A marker. RD and MOL.

Walter Gates, BLM representative, was on location. Jim Morris, MVCI representative was on location.