

RECEIVED

Form 3160-5
(August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

AUG 31 2012

FORM APPROVED
OMB No 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5 Lease Serial No NM-32124
6 If Indian, Allottee or Tribe Name N/A

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1 Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		7. If Unit of CA/Agreement, Name and/or No
2 Name of Operator Encana Oil & Gas (USA) Inc.		8. Well Name and No Good Times A06-2310 01H
3a. Address 370 17th Street, Suite 1700 Denver, CO 80202	3b. Phone No. (include area code) 720-876-3437	9 API Well No 30-045-35319
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL: 920' FNL and 215' FEL Section 6, T23N, R10W BHL: 920' FNL and 330' FWL Section 6, T23N, R10W		10. Field and Pool or Exploratory Area South Bisti-Gallup (5860)
		11. Country or Parish, State San Juan, New Mexico

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input checked="" type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plugged the motherbore between 8/10/12 and 8/11/12. Please see attached Motherbore Plug Back Procedure.

CONFIDENTIAL

RCVD SEP 14 '12
OIL CONS. DIV.
DIST. 3

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Amanda Cavoto	Title Engineering Technologist
Signature <i>Amanda Cavoto</i>	Date 08/30/12

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by	Title	Date SEP 06 2012
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	FARMINGTON FIELD OFFICE BY <i>[Signature]</i>

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

NMOCD AV

Good Times A06-2310 01H
API: 30-045-35319
Motherbore Plug Back Procedure

TOPS:	TVD
KOP	3873'
Graneros Shale	5327'
Dakota	5367'

Set 2 cement plugs in 8 ½" hole
Plug A: Bottom plug over Dakota
Plug B: Kick plug at KOP

Plug A (operations conducted 8/10/12)

1. TIH to TD of vertical pilot hole at 5746'
2. Spot 461' cement plug from 5285' - 5746'
 - a. 145sx of Type III cement + 1% CaCl₂ + 0.25#/sk Celloflake + 0.2% FL-52A
(Mixed at 14.63ppg, 1.38ft³/sk yield)
 - b. Spot tuned spacer
3. Pull uphole and reverse out
4. TIH and tag plug, proceed when cement is solid
5. Fill hole and move uphole to spot kick plug

Plug B (operations conducted 8/11/12)

1. Spot 485' kick plug from 3526' - 4011'
 - a. 219sx of Type G cement w/0.04% Static Free + 0.9% CD-32 + 0.005 gps FP-6L + 0.1% BA-59 + 0.1% R-2
(Mixed at 17.5ppg, 0.95ft³/sk yield)
 - b. Spot tuned spacer
2. Pull uphole and reverse out
3. Pump bottoms up 2 times, pull uphole
4. Tag plug, drill ahead to KOP when cement is solid