Form 3160-5 (August 2007)

FORM APPROVED OMB No 1004-0137

	BUREAU OF LAND MAI	NAGEMENT	Expires	July 31, 2010	
		SEP 19 201		E. 077107. A	
SUN	IDRY NOTICES AND REP	ORTS ON WELLS - Fiold	Office#f Indian. Allottee or Tribe	F-077107-A Name	
Do not use	DRY NOTICES AND REPORT IN THE PROPERTY IN THE	to drill or to re-enter attan	agemen		
abandoned	well. Use Form 3160-3 (A	(PD) for such proposals.			
SUBMIT IN TRIPLICATE - Other instructions on page 2			7 If Unit of CA/Agreement, N		
1 Type of Well					
Oil Well X Gas Well Other			8 Well Name and No.	8 Well Name and No.	
		· · · · · · · · · · · · · · · · · · ·	Ha	Hancock B 12	
2 Name of Operator Burlington Resources Oil & Gas Company LP			9 API Well No	0.45 0.4504	
PO Box 4289, Farmington, NM 87499		3b Phone No (include area code)			
		(505) 326-9700		Otero Chacra / Basin FC	
4 Location of Well (Footage, Sec., T.,R,M, or Survey Description)			11 Country or Parish, State		
Surface Unit L (N	WSW), 1745' FSL & 840' F	WL, Sec. 28, T28N, R9W	San Juan	, New Mexico	
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF N	NOTICE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
	Change Plans	X Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
determined that the site is ready for	Abandonment Notices must be filed o final inspection.) well was P & A d on		R	nd the operator has CVD SEP 21'12 DIL CONS. DIV. DIST. 3	
14 Thereby certify that the foregoing is to Dollie L. Busse Signature	rue and correct Name (Printed/Type		atory Technician		
	THIS SPACE FOR	R FEDERAL OR STATE O	FFICE USE	SEPTED FOR RECOR	

SEP 2 0 2012 Title FARMINGTON FIELD OFFICE Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon

Title 18 U.S.C Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction of false, fictition on page 2)

m

(Instruction on page 2)

Approved by

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Hancock B #12

August 20, 2012 Page 1 of 1

1745' FSL and 840' FWL, Section 28, T-28-N, R-9-W San Juan County, NM Lease Number: SF-077107-A API #30-045-21561

Plug and Abandonment Report Notified NMOCD and BLM on 8/13/12

Plug and Abandonment Summary:

- Plug #1 pump 10 sxs (11.8 cf) Class B cement inside casing from 3122' to 2759' to cover the Chacra top.
- Plug #2 pump 16 sxs (18.88 cf) Class B cement inside casing from 2257' to 1675' to cover the Pictured Cliffs and Fruitland top.
- Plug #3 pump 10 sxs (11.8 cf) Class B cement inside casing from 1343' to 980' to cover the Kirtland and Ojo Alamo top.
- Plug #4 with 76 sxs (surface) Class B cement inside casing from 166' to surface.
- Plug #5 pump 24 sxs (28.32 cf) Class B cement to top off casings and install P&A marker.

Plugging Work Details:

- 8/14/12 MOL & RU. SDFD.
- 8/15/12 Open up well; no pressures. NU BOP and test. PU one concave mill 1", bit sub 1" x 1" change over bit sub 1"x1 13/16 and tubing workstrip. TIH and tag sand at 2981'.Note: existing CIBP at 3000'. SI well. SDFD.
- 8/16/12 Open up well; no pressures. RU Power Swivel break circulation. Tag fill at 2981' and clean out to 3000'. Drill out plug to CIBP at 3122'. Circulate well clean. SI well. SDFD.
- 8/17/12 Open up well; no pressures. Tally TIH with open-ended tubing and tag existing CIBP at 3122'. Spot plugs #1, #2 and #3. Establish circulation. LD all tubing. Perforate 3 HSC holes at 116'. POH. Establish circulation out of bradenhead. Spot plug #4. SI well. SDFD.
- 8/20/12 Travel to location. Open up well; no pressures. ND BOP. Fill out Hot Work Permit. Dig out wellhead and cut off. Found cement down 5' bradenhead and 20' in 2 7/8 casing. Spot Plug #5 and install P&A marker. RD & MOL.
 - R. Bixler, Conoco representative, was on location. Joe Ruybalid, BLM representative, was on location.