PN

Office	State of New Me			Form C-103
1625 N. French Dr., Hobbs, NM 88240	nergy, Minerals and Natu	ral Resources	WELL API NO.	March 4, 2004
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION 1220 South St. Fran	DIVISION	30-045-24691 5. Indicate Type of	Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran	ncis Dr.	STATE [FEE 🛚
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	7505 5 2004	6. State Oil & Gas	Lease No.
SUNDRY NOTICES A (DO NOT USE THIS FORM FOR PROPOSALS TO	ND REPORTS ON WELLS DO DRILL OR TO DEEPEL OR TO	LIG BACK TO A		Jnit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	FOR PERMIT" (FORM C-101) FO	0K SUCH	Palmer 8. Well Number	
1. Type of Well: Oil Well ☐ Gas Well ☒ Other	10 m c	The state of the s	#1	
	- Ju		9. OGRID Number	
Name of Operator Richardson Operating Company	E notes	2004	019219	·
3. Address of Operator			10. Pool name or V	· · · · · · · · · · · · · · · · · · ·
3100 La Plata Highway, Farmington, N	IM 87401 🛴 🍇		West Kutz Picture	d Cliffs
4. Well Location	No.	e Sign		
Unit LetterG:1735'_	_feet from theNorth_/	line and 169	95'feet from the	Eastline
		didon large degree		İ
Section 17	Township 29N Devation (Show whether DR	Range 13W RKB, RT, GR, etc.)		County San Juan
5244' GL				
Pit or Below-grade Tank Application (For pit or b				
Pit Location: ULSectTwpRng				rest fresh water well
Distance from nearest surface waterB feet from theline andf		SectIwp_	;	
leet from the fine and	eet from thenne			
12. Check Approp	oriate Box to Indicate N	lature of Notice, l	Report or Other D	Data
NOTICE OF INTENT	TION TO:	CLID		
			SEQUENT REP	
PERFORM REMEDIAL WORK PLUC				ORT OF: ALTERING CASING
PERFORM REMEDIAL WORK PLUG			.LING OPNS. \Box F	ALTERING CASING PLUG AND
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA	G AND ABANDON	REMEDIAL WORK	.LING OPNS.□ F	ALTERING CASING
PERFORM REMEDIAL WORK PLUC TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL	G AND ABANDON NGE PLANS	REMEDIAL WORK	.LING OPNS.□ F	ALTERING CASING PLUG AND
PERFORM REMEDIAL WORK PLUC TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL	G AND ABANDON NGE PLANS TIPLE	REMEDIAL WORK COMMENCE DRILL CASING TEST AN	.LING OPNS.□ F	ALTERING CASING PLUG AND
PERFORM REMEDIAL WORK PLUC TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM	G AND ABANDON NGE PLANS TIPLE IPLETION	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER:	LING OPNS. F	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Si	G AND ABANDON NGE PLANS TIPLE IPLETION perations. (Clearly state all	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and	LING OPNS. F	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Si or recompletion.	G AND ABANDON NGE PLANS TIPLE IPLETION Departions. (Clearly state all EE RULE 1103. For Multip	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ile Completions: Att	LING OPNS. F	PLUG AND ABANDONMENT , including estimated date in of proposed completion
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Single or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cem	G AND ABANDON NGE PLANS TIPLE IPLETION perations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at nent on perfs. Shut in at 5	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31s	LLING OPNS. F	ALTERING CASING PLUG AND ABANDONMENT , including estimated date of proposed completion , 15.6ppg, 1.18 yield, at
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Si or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cemp&A marker. Clean up location. Prept	G AND ABANDON NGE PLANS TIPLE IPLETION perations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at nent on perfs. Shut in at 5	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31s	LLING OPNS. F	ALTERING CASING PLUG AND ABANDONMENT , including estimated date of proposed completion , 15.6ppg, 1.18 yield, at
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Single or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cem	G AND ABANDON NGE PLANS TIPLE IPLETION perations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at nent on perfs. Shut in at 5	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31s	LLING OPNS. F	ALTERING CASING PLUG AND ABANDONMENT , including estimated date of proposed completion , 15.6ppg, 1.18 yield, at
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Since or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cementers. P&A marker. Clean up location. Prep to 7/1/04 Finish location cleanup.	G AND ABANDON NGE PLANS TIPLE IPLETION perations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at nent on perfs. Shut in at 5 to reclaim. Witnessed by	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ile Completions: Att 250psi. Pump 31s 500psi. Bring ceme Henry V. with OCI	LING OPNS. F B Give pertinent dates ach wellbore diagrames Class B cement nt to surface. Cut D.	ALTERING CASING DELUG AND ABANDONMENT , including estimated date of proposed completion , 15.6ppg, 1.18 yield, at off wellhead. Install
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Si or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cemp&A marker. Clean up location. Prept	G AND ABANDON NGE PLANS TIPLE IPLETION perations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at nent on perfs. Shut in at 5 to reclaim. Witnessed by is true and complete to the b	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31s 500psi. Bring ceme Henry V. with OCI	LING OPNS. F B Give pertinent dates ach wellbore diagrament to surface. Cut D.	ALTERING CASING DELUG AND ABANDONMENT , including estimated date of proposed completion 15.6ppg, 1.18 yield, at off wellhead. Install
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Since or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cementers. P&A marker. Clean up location. Prep to 7/1/04 Finish location cleanup. I hereby certify that the information above.	G AND ABANDON NGE PLANS TIPLE IPLETION Decrations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at the nent on perfs. Shut in at 5 to reclaim. Witnessed by is true and complete to the becording to NMOCD guidelines [COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31: 500psi. Bring ceme Henry V. with OCI	LING OPNS. F B B Give pertinent dates ach wellbore diagram EX Class B cement nt to surface. Cut Control of the control of	ALTERING CASING DUG AND ABANDONMENT Including estimated date of proposed completion and proposed completion and proposed completion are off wellhead. Install certify that any pit or belowive OCD-approved plan
PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHA PULL OR ALTER CASING MUL COM OTHER: 13. Describe proposed or completed of of starting any proposed work). Since or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cementers. P&A marker. Clean up location. Prep to 7/1/04 Finish location cleanup. I hereby certify that the information above the grade tank has been/will be constructed or closed as a constructed or closed as constructed o	G AND ABANDON NGE PLANS TIPLE IPLETION Decrations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at the nent on perfs. Shut in at 5 to reclaim. Witnessed by is true and complete to the becording to NMOCD guidelines [COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31: 500psi. Bring ceme Henry V. with OCI	LING OPNS. F B B Give pertinent dates ach wellbore diagram EX Class B cement nt to surface. Cut Control of the control of	ALTERING CASING DELUG AND ABANDONMENT , including estimated date of proposed completion , 15.6ppg, 1.18 yield, at off wellhead. Install certify that any pit or belowive OCD-approved plan
PERFORM REMEDIAL WORK PLUC TEMPORARILY ABANDON CHA PULL OR ALTER CASING MULCOM OTHER: 13. Describe proposed or completed or of starting any proposed work). Since or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cementers. P&A marker. Clean up location. Prep to 7/1/04 Finish location cleanup. I hereby certify that the information above is grade tank has been/will be constructed or closed a SIGNATURE Clark H. Williams Type or print name Charks H. Williams (This space for State use)	GAND ABANDON NGE PLANS TIPLE IPLETION Decrations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at the nent on perfs. Shut in at 5 to reclaim. Witnessed by is true and complete to the becording to NMOCD guidelines [TITLE 2 E-mail act 2 to 2	COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31s 500psi. Bring ceme Henry V. with OCI est of my knowledge , a general permit Eng. weering Open didress: ON Name of	LING OPNS. F B B Give pertinent dates ach wellbore diagram EX Class B cement nt to surface. Cut Contact and belief. I further or an (attached) alternate of the contact action of the contact act	ALTERING CASING DUG AND ABANDONMENT Including estimated date of proposed completion and proposed completion and proposed completion are off wellhead. Install certify that any pit or belowive OCD-approved plan
PERFORM REMEDIAL WORK PLUC TEMPORARILY ABANDON CHA PULL OR ALTER CASING MULCOM OTHER: 13. Describe proposed or completed or of starting any proposed work). Since or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cementers. P&A marker. Clean up location. Prep to 7/1/04 Finish location cleanup. I hereby certify that the information above is grade tank has been/will be constructed or closed a SIGNATURE Clark H. Williams Type or print name Charks H. Williams (This space for State use)	GAND ABANDON NGE PLANS TIPLE IPLETION Decrations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at the nent on perfs. Shut in at 5 to reclaim. Witnessed by is true and complete to the becording to NMOCD guidelines [TITLE 2 E-mail act 2 to 2	COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31s 500psi. Bring ceme Henry V. with OCI est of my knowledge , a general permit Eng. weering Open didress: ON Name of	LING OPNS. F B B Give pertinent dates ach wellbore diagram EX Class B cement nt to surface. Cut Contact and belief. I further or an (attached) alternate of the contact action of the contact act	ALTERING CASING DUG AND ABANDONMENT Including estimated date of proposed completion and proposed completion and proposed completion are off wellhead. Install certify that any pit or belowive OCD-approved plan
PERFORM REMEDIAL WORK PLUC TEMPORARILY ABANDON CHA PULL OR ALTER CASING MULCOM OTHER: 13. Describe proposed or completed or of starting any proposed work). Since or recompletion. 6/17/04 MIRU cementers. Est. rate of 200 psi., 1.5bpm. Locked up when cementers. P&A marker. Clean up location. Prep to 7/1/04 Finish location cleanup. I hereby certify that the information above is grade tank has been/will be constructed or closed a SIGNATURE Clark H. Williams Type or print name Charks H. Williams (This space for State use)	G AND ABANDON NGE PLANS TIPLE IPLETION Decrations. (Clearly state all EE RULE 1103. For Multip 2 bpm down 2 7/8" csg at the nent on perfs. Shut in at 5 to reclaim. Witnessed by is true and complete to the becording to NMOCD guidelines [COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: pertinent details, and ale Completions: Att 250psi. Pump 31s 500psi. Bring ceme Henry V. with OCI est of my knowledge , a general permit Eng. weering Open didress: ON Name of	LING OPNS. F B B Give pertinent dates ach wellbore diagram EX Class B cement nt to surface. Cut Contact and belief. I further or an (attached) alternate of the contact action of the contact act	ALTERING CASING DUG AND ABANDONMENT Including estimated date of proposed completion and proposed completion and proposed completion are off wellhead. Install certify that any pit or belowive OCD-approved plan