

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ConocoPhillips Co.

3a. Address

P.O. Box 2197, WL3-6081 Houston Tx 77252

3b. Phone No. (include area code)

(832)486-2463

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 9 T24N R5W SWSE 990FSL 1830FEL

5. Lease Serial No.

JIC36

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Northeast Haynes #1E

9. API Well No.

30-039-22320

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

Rio Arriba

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Attempt to Restore Prod.</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Jicarilla Contract 36 et al. (WC)
3162.3-2 (21110)

Rig work done 5/17/05 to replace tubing hanger seals. Swabbed well. Produced 40 bbls of water. Will continue to swab. Daily summary report attached.

2005 JUN 15 PM 12 22
RECEIVED
070 FARMINGTON NM

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Christina Gustartis

Title

Regulatory Analyst

Signature

Christina Gustartis

Date

06/14/2005

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

JUN 20 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

BY *sm*

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOC

Surface Equipment Work, 05/16/2005 09:30

API/Bottom UWI 300392232000	County RIO ARRIBA	State/Province NEW MEXICO	Surface Legal Location NMPM-24N-5W-9-O	N/S Dist (ft) 990.00	N/S Ref S	E/W Dist (ft) 1,830.00	E/W Ref E
Ground Elevation (ft) 6,531.00	Latitude (DMS) 36° 19' 21.576" N	Longitude (DMS) 107° 21' 45.72" W	Spud Date 11/25/1980	Rig Release Date			

05/16/2005 09:30 - 05/16/2005 18:30

Last 24hr Summary

Move unit to NEH #1E. Hold safety meeting and review JSA. Check LOTO and LEL. Check pressures: tbg - 250 psi; csg - 400 psi. Move equipment onto location and rig up. Rig up wireline and retrieve plunger. Set wireline plug in F nipple. Fluid level in well @ 5350'. Remove wellhead, set in and nipple up BOP. Rig up floor. Pressure test tbg to 500 psi for 15 min. Good test. Pull tbg hanger and install new "O" ring seals (one seal missing; 1 seal had been leaking). Change out one 2-1/16" csg valve. Nipple down and set out BOP and install tree. Secure well and location and SDFN.

05/17/2005 08:00 - 05/17/2005 10:00

Last 24hr Summary

Hold safety meeting and review JSA. Check pressure. SICP - 400 psi. Rig up slickline unit and retrieve plug. Fluid level @ 4950'. Rig down and prepare to move to NEH # 8E. Rig released @ 10:00



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington Field Office
1235 La Plata Highway, suite A
Farmington, New Mexico 87401

IN REPLY REFER TO:

Jicarilla Contract 36 et al. (WC)
3162.3-2 (21110)

June 1, 2005

Ms. Yolanda Perez
ConocoPhillips Co.
PO Box 2197, 3WL 6106
Houston, TX 77252

Dear Ms. Perez:

Our records indicate that you are the operator of the following wells:

- 1) No. 1E NE Haynes located 990' FSL & 1830' FEL sec. 9, T. 24 N., R. 5 W., Rio Arriba County, New Mexico, Lease Jicarilla Contract 36. Well has not produced since May, 2004.
- 2) No. 2E NE Haynes located 1850' FNL & 1840' FEL sec. 16, T. 24 N., R. 5 W., Rio Arriba County, New Mexico, Lease Jicarilla Contract 36. Well has not produced since May, 2004.
- 3) No. 10 Jicarilla 30 located 330' FSL & 660' FWL sec. 30, T. 25 N., R. 4 W., Rio Arriba County, New Mexico, Lease Jicarilla Contract 41. Well has not produced since May, 2004.
- 4) No. 11 Jicarilla 30 located 1650' FNL & 1650' FWL sec. 30, T. 25 N., R. 4 W., Rio Arriba County, New Mexico, Lease Jicarilla Contract 41. Well has not produced since May, 2004.
- 5) No. 12 Jicarilla 20 located 1785' FNL & 335' FWL sec. 18, T. 25 N., R. 4 W., Rio Arriba County, New Mexico, Lease Jicarilla Contract 64. Well has not produced since May, 2004.

Title 43 CFR Section 3162.3-4 requires that the lessee shall promptly plug and abandon, condition as a service well, or condition as a water well, any well on a lease that is not used or useful for the purpose of the lease. Accordingly, you are required to advise this office by Sundry Notice within 30 calendar days of your intent to perform one of the following: a) Condition the well to a useful function, b) Temporarily abandon the well, c) Continued shut-in status, d) Permanently plug and abandon the well.

See attached General Requirements for Non-Producing wells on Federal leases.

The 30 calendar days commences upon receipt of this letter or seven days from the date it is mailed, whichever is less. Failure to comply within the 30 calendar days may result in an assessment in accordance with 43 CFR 3163.1.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the orders described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management (NM-93000), P. O. Box 27115, Santa Fe, New Mexico 87502-0115. Such request shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 *et seq.*