Form 3160- 5					
September 2001)		) STATES )F THE INTERIOR			FORM APPROVED OMB No. 1004- 0135
	BUREAU OF LAN				Expires: January 31,2004
CID				5. Lease Serial	
	DRY NOTICES AN			6. If Indian, All	SF079601 lottee, op Tribe Name
	indoned well. Use Form 31				
SUBMIT IN TR	IPLICATE - Other In	structions on rever	se side	7. If Unit or CA	A. Agreement Designation
Oil Well X Gas Well	Other	678	391077	8. Well Name a	
2. Name of Operator		A.	1. 51 CA	Lydia Rent: 9. API Well No	
Four Star Oil & Gas Compa 3a. Address	uny	3b. Phone No <sup>S</sup> (in	clude after code)		30-039-25316-00
11111 Wilcrest, Rm-122	2, Houston, Texas 770	)99 (281)	561-4991 -		ool, or Exploratory Area
4. Location of Well (Footage, Sec., 7	, R., M., or Survey Description)				Lindrith West
		. 18		11. County or F	
990' FSL & 1650' FWL / Sec.		<b>T</b>	<u>////</u>	• • • • • • • • • • • • • • • • • • • •	Arriba New Mexico
	PRIATE BOX(S) TO IN	<u></u> <u></u>	171 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	RT, OR OTH	ER DATA
TYPE OF SUBMISSION			YPE OF ACTION		
X Notice of Intent	Acidize	Deepen	Production ( S	tart/ Resume)	Water Shut-off
	Altering Casing	Fracture Treat	Reclamation		Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete		Other
	Change Plans	Plug and abandon			L
				Adandon	·····
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for	work will performed or provide yed operations. If the operation Abandonment Notice shall be fi	results in a multiple completi	BLM/ BIA. Required su ion or recompletion in a n	bsequent reports s ew interval, a For	shall be filed within 30 days rm 3160-4 shall be filed once
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready fo Four Star Oil & Procedure:	work will performed or provide ved operations. If the operation Abandonment Notice shall be fi or final inspection.) Gas Company prposes	the Bond No. on file with the results in a multiple completi led only after all requiremen s to Plug & Abandor	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion the subject well	bsequent reports s ew interval, a Fou , have been comp as follows:	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready fo Four Star Oil & Procedure:	work will performed or provide ved operations. If the operation of Abandonment Notice shall be fi or final inspection.)	the Bond No. on file with the results in a multiple completi led only after all requiremen s to Plug & Abandor	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion the subject well	bsequent reports s ew interval, a Fou , have been comp as follows:	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and	work will performed or provide ved operations. If the operation i Abandonment Notice shall be fi or final inspection.) Gas Company prposes test rig anchors. Prepa	the Bond No. on file with the results in a multiple completi led only after all requiremen s to Plug & Abandor are blow pit. Compl	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion n the subject well y w/all BLM and	bsequent reports s ew interval, a For , have been comp as follows: Chevron HE	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has CS Regulations.
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO	work will performed or provide ved operations. If the operation Abandonment Notice shall be fi or final inspection.) Gas Company prposes	the Bond No. on file with the results in a multiple completi led only after all requiremen s to Plug & Abandor are blow pit. Compl meeting w/all perso	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion n the subject well y w/all BLM and nnel on location.	bsequent reports s ew interval, a Foi , have been comp as follows: Chevron HE NU relief lin & pump.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations. ne. Bloxy down well a
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fi or final inspection.) Gas Company prposes test rig anchors. Prepa O Rig. Conduct safety	the Bond No. on file with the results in a multiple completi led only after all requiremen s to Plug & Abandor are blow pit. Compl meeting w/all perso	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion n the subject well y w/all BLM and nnel on location.	bsequent reports s ew interval, a Foi , have been comp as follows: Chevron HE NU relief lin & pump.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations. ne. Bloxy down well a
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fi- for final inspection.) Gas Company prposes test rig anchors. Preps O Rig. Conduct safety ter in necessary. Unse	the Bond No. on file with the results in a multiple completi led only after all requiremen as to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg fo	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion n the subject well y w/all BLM and nnel on location. or leaks. Pull rods	bsequent reports s ew interval, a Foi , have been comp as follows: Chevron HE NU relief lin & pump.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations. The. Blow, down wells 0 1 1 1 1 1 1 1 1 1 1
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh 4. TOOH w/	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fir or final inspection.) Gas Company prposes test rig anchors. Prepa D Rig. Conduct safety ter in necessary. Unse ead., NU BOP's.	the Bond No. on file with the results in a multiple completi led only after all requiremen s to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for w/GR/JB and tag to f	BLM/ BIA. Required su ion or recompletion in a n is, including reclamantion n the subject well y w/all BLM and nnel on location. For leaks. Pull rods	bsequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations.
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH with	work will performed or provide ved operations. If the operation i Abandonment Notice shall be fi or final inspection.) Gas Company prposes test rig anchors. Preps O Rig. Conduct safety ter in necessary. Unse ead., NU BOP's.	the Bond No. on file with the results in a multiple completi led only after all requiremen is to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for w/GR/JB and tag to for ith packer and set @	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion n the subject well y w/all BLM and nnel on location. Find top of fish (sh 27060'. Test csg t	bsequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump.	Shall be filed within 30 days fm 3160-4 shall be filed once pleted, and the operator has ES Regulations.
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready fo Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH wit 6. TOOH wit	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fir or final inspection.) Gas Company prposes test rig anchors. Prepa O Rig. Conduct safety ter in necessary. Unse ead., NU BOP's. 22-7/8" tubing. RIH with th workstring. RIH with	the Bond No. on file with the results in a multiple completi led only after all requiremen as to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for v/GR/JB and tag to f ith packer and set @ ker. TIH with CIBP	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion n the subject well y w/all BLM and nnel on location. or leaks. Pull rods find top of fish (sh 27060'. Test csg f set @7960'.	bsequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump. hould tag arc o 500psi.	Shall be filed within 30 days fm 3160-4 shall be filed once pleted, and the operator has ES Regulations.
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH with 6. TOOH with 7. Plug #1: 7	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fib or final inspection.) Gas Company prposes test rig anchors. Prepa D Rig. Conduct safety ter in necessary. Unse ead., NU BOP's. 22-7/8" tubing. RIH with workstring. RIH with th workstring and pack	the Bond No. on file with the results in a multiple completi led only after all requiremen is to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for w/GR/JB and tag to f ith packer and set @ ker. TIH with CIBP sks on top CIBP and	BLM/ BIA. Required su ion or recompletion in a n is, including reclamantion in the subject well y w/all BLM and nnel on location. find top of fish (sh 27060'. Test csg t set @7960'. TOOH with work	bsequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump. hould tag arc to 500psi. cstring.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations.
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH with 6. TOOH with 7. Plug #1: 7	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fi- or final inspection.) Gas Company prposes test rig anchors. Prepa D Rig. Conduct safety ter in necessary. Unse ead., NU BOP's. ' 2-7/8" tubing. RIH wi th workstring. RIH wi th workstring and pack 960'-7779'. Pump 50 s BP and set @7020'. P	the Bond No. on file with the results in a multiple completi led only after all requiremen is to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for w/GR/JB and tag to f ith packer and set @ ker. TIH with CIBP sks on top CIBP and	BLM/ BIA. Required su ion or recompletion in a n is, including reclamantion in the subject well y w/all BLM and nnel on location. find top of fish (sh 27060'. Test csg t set @7960'. TOOH with work	bsequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump. hould tag arc to 500psi. cstring.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations.
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready fo Four Star Oil & Procedure: 1. Install and 2. MIRU WC kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH wit 6. TOOH wit 7. Plug #1: 7 8. RIH w/CI	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fi- or final inspection.) Gas Company prposes test rig anchors. Prepa D Rig. Conduct safety ter in necessary. Unse ead., NU BOP's. ' 2-7/8" tubing. RIH wi th workstring. RIH wi th workstring and pack 960'-7779'. Pump 50 s BP and set @7020'. P	the Bond No. on file with the results in a multiple completi led only after all requiremen is to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for w/GR/JB and tag to f ith packer and set @ ker. TIH with CIBP sks on top CIBP and	BLM/ BIA. Required su ion or recompletion in a n is, including reclamantion in the subject well y w/all BLM and nnel on location. find top of fish (sh 27060'. Test csg t set @7960'. TOOH with work	bsequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump. hould tag arc to 500psi. cstring.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations. The. Blow down well of RECONNERS NOTIFICATION OF THE STREET Street Street Stree
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH with 6. TOOH with 7. Plug #1: 7 8. RIH w/CI 14. 1 hereby certify that the foregoing Name (Printed' Typed)	work will performed or provide ved operations. If the operation in Abandonment Notice shall be fi- or final inspection.) Gas Company prposes test rig anchors. Prepa D Rig. Conduct safety ter in necessary. Unse ead., NU BOP's. ' 2-7/8" tubing. RIH wi th workstring. RIH wi th workstring and pack 960'-7779'. Pump 50 s BP and set @7020'. P	the Bond No. on file with the results in a multiple completi led only after all requiremen is to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for w/GR/JB and tag to f ith packer and set @ ker. TIH with CIBP sks on top CIBP and U and test casing to	BLM/ BIA. Required su ion or recompletion in a n is, including reclamantion in the subject well y w/all BLM and nnel on location. find top of fish (sh 27060'. Test csg t set @7960'. TOOH with work	beequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump. hould tag arc to 500psi. cstring.	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations. The. Blow down well of RECONNECTION NOTION 29 Sound +/-7982').
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WO kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH with 6. TOOH with 7. Plug #1: 7 8. RIH w/CI 14. 1 hereby certify that the foregoing Name (Printed' Typed)	work will performed or provide ved operations. If the operation i Abandonment Notice shall be fi or final inspection.) Gas Company prposes test rig anchors. Prepa D Rig. Conduct safety ter in necessary. Unse ead., NU BOP's. ' 2-7/8" tubing. RIH wi th workstring. RIH wi th workstring and pack 960'-7779'. Pump 50 s BP and set @7020'. P	the Bond No. on file with the results in a multiple completi led only after all requiremen is to Plug & Abandor are blow pit. Completing meeting w/all perso eat pump. Test tbg for v/GR/JB and tag to for ith packer and set @ ith packer and set @ ith packer and set @ ith packer and set @ ith cliBP sks on top ClBP and U and test casing to Title Date	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion in the subject well y w/all BLM and nnel on location. or leaks. Pull rods find top of fish (sh 27060'. Test csg t set @7960'. TOOH with work ensure you're abo	beequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump. hould tag arc o 500psi. cstring. exerting. Regulatory Sp 5	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations. The. Blow down well of RECONNECTION NOTION 29 Sound +/-7982').
Attach the Bond under which the v following completion of the invol- testing has been completed. Final determined that the site is ready for Four Star Oil & Procedure: 1. Install and 2. MIRU WC kill w/wa 3. ND Wellh 4. TOOH w/ 5. TOOH wit 6. TOOH wit 7. Plug #1: 7 8. RIH w/CI 14. 1 hereby certify that the foregoing Name (Printed/ Typed) Kenneth W. Jackson	work will performed or provide ved operations. If the operation i Abandonment Notice shall be fi or final inspection.) Gas Company prposes test rig anchors. Prepa D Rig. Conduct safety ter in necessary. Unse ead., NU BOP's. ' 2-7/8" tubing. RIH wi th workstring. RIH wi th workstring and pack 960'-7779'. Pump 50 s BP and set @7020'. P	the Bond No. on file with the results in a multiple completi led only after all requiremen is to Plug & Abandor are blow pit. Compl meeting w/all perso eat pump. Test tbg for v/GR/JB and tag to f ith packer and set @ ker. TIH with CIBP sks on top CIBP and U and test casing to	BLM/ BIA. Required su ion or recompletion in a n ts, including reclamantion in the subject well y w/all BLM and nnel on location. or leaks. Pull rods find top of fish (sh 27060'. Test csg t set @7960'. TOOH with work ensure you're abo	beequent reports s ew interval, a For , have been comp as follows: Chevron HE NU relief lin & pump. hould tag arc o 500psi. cstring. exerting. Regulatory Sp 5	shall be filed within 30 days rm 3160-4 shall be filed once pleted, and the operator has ES Regulations. The. Blow down well of RECONNECTION NOTION 29 Sound +/-7982').

ŧ

1

ß

Approved by Original Signed: Stephen Mason Interview of the approval, if any are attached. Approval of this notice foes not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or representations as to any matter within its jurisdiction.

WELL: LYDIA RENTZ 9 990' FSL & 1650' FWL SEC. 20, T25N, R3W RIO ARRIBA COUNTY, NM

API: 30-039-25316

9. Plug #2: 7020' - 6720'. Spot 12 sks (100') on top of CIBP.
Image: Spot 12 sks (100') on top of CIBP.
Image: Plug #3: 4635'-4735. Pump 12 sks (100') balance plug (Cha cra) 3816 3362
11. Plug #4: 3956'-3444'. Pump 60 sks (544') balance plug. Plug Macimin ro 2152'-2052' Plug Sorf-ce Caning shale 500'-400' 12. Plug #5: 90' - 0'. Pump 10 sks balance plug from 90' to surface.

13. ND BOP and RD W/O rig. Dig cellar and cut off wellhead & top of casing strings as needed. Move off location. Cut off anchors and install dry hole marker





## Lydia Rentz 9 Blanco MV Current Schematic

