

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NMSF078089

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

XTO Energy Inc.

3a. Address

2700 Farmington Ave., Bldg. K, Ste 1 Farmington,

3b. Phone No. (include area code)

505-324-1090

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FSL & 1520' FWL, UL N, SEC 36-T27N-R11W

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

SCOTT E FEDERAL #18

9. API Well No.

30-045-24569

10. Field and Pool, or Exploratory Area
BASIN FRUITLAND COAL

11. County or Parish, State

SAN JUAN

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. plugged & abandoned this well in following manner:

Rptd to BLM & NMOC 7/16/05 of P&A operations for 7/21/05. MIRU P&A rig. ND WH. NU BOP. TOH w/tbg. MIRU WLJ. PT csg; held OK. Ppd plug #1 w/11 sx Type III cmt (14.8 ppg & 1.32 cuft/sx). Ppd dwn tbg w/2.3 bbls cmt fr/1775'--1412'/ TOHw/IJ tbg. Tgd TOC fr/plug #1 @ 1328'. Ppd plug #2 w/10 sx Type III cmt (14.8 ppg, 1.32 cuft'. Ppd plug #3 w/14 sx type III cmt (14.8 ppg, 1.32 cuft/sx). Ppd dwn tbg w/2.9 bbls cmt. cmt fr/225' to surf. RDMO #9 rig. Dig out WH. cur off tbg. Installed dry hole marker w/20 sx type III cmt. Cut off anchors. Cleaned location. P&A completed. Marvin Hurtley & Deam Admas 2/BLM on loc to witness.

1161'-755'

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

HOLLY C. PERKINS

Title

REGULATORY COMPLIANCE TECH

Date 7/29/2005

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date AUG 03 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE
BY *Spur*

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 * fax: 505-325-1211

XTO Company
Scott E. Federal #18

July 22, 2005

Page 1 of 1

990' FSL & 1520' FWL, Section 36, T-27-N, R-11-W
San Juan County, NM
NMSF-078089
API #30-045-24569

Plug & Abandonment Report

Summary:

Notified BLM on 7/15/05

7/20/05 MOL. RU equipment. Well pressures: 150# casing, 120# tubing and 0# bradenhead. Kill well with 1 bbls of water. ND wellhead. Strip on 2-7/8" tubing head with BOP, test. Shut in well.

7/21/05 TOH and LD 57 joints 1.25" tubing. Pressure test bradenhead to 300#. TIH with 2-7/8" casing gauge ring to 1813'. TIH and set 2-7/8" DHS CIBP at 1775'. TIH with 55 joints 1.25" IJ tubing and tag BP at 1775'. Circulate well clean with 12 bbls of water. Pressure test casing to 600# for 30 minutes.

Plug #1 with BP at 1775', spot 11 sxs Type III cement (15 cf) inside casing from 1775' to 1328' to isolate Pictured Cliffs interval and cover Fruitland top. PUH to 1161'.

Plug #2 mix 10 sxs Type III cement (13 cf) and spot a balanced plug inside casing from 1161' to 755' to cover the Kirtland top and Ojo Alamo top. TOH to 225'.

Plug #3 mix and pump 14 sxs Type III cement (19 cf) from 225' to surface, circulate good cement out casing valve.

Shut in well. ND BOP. Dig out and cut off wellhead. Found cement down 20' in 2-7/8" casing and down 8' in 7" casing annulus. Fill casings and install P&A marker with 15 sxs Type III cement.

RD and MOL.

M. Huntley and D. Adams, BLM, visited location on 7/21/05.