

GENERAL MINERALS CORPORATION
4133 N. LINCOLN BLVD.


2005 AUG 8 PM 1 45

OKLAHOMA CITY, OK 73105
405-524-5227; Fax-405-524-5229

RECEIVED

070 FARMINGTON NM
Steve Mason, Petroleum Engineer
BLM, State Director
Bureau of Land Management
MM-93000
P.O. Box 27115, Santa Fe, N.M. 87502-0115
505-599-6364

7/25/05



Ref; Indian Bend #3 located at 1000 FNL, 1850 FWL, section 26, T23N, R3w, Sandoval County, N.M.; lease Jicarilla contract 55A

Steven Mason,

30-043-20562


We are responding to your letter dated June 22, 2005 regarding no production on Indian Bend#3.

The subject well had accumulated too much condensate mixed with water. The perforations had been partially plugged up. These problems have been corrected.

Along with El Paso Natural Gas reducing the line pressure within the last week has made it possible to produce this well. El Paso has assured us that they will flip the gas meter chart on this Thursday as the well is now capable of producing.

Consequently, the well is being returned to production.

Sincerely,


Kris K. Agrawal
Engineer

NMOCD