Submit 3 Copies To Appropriate District Office <u>District 1</u>	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240 Dist <u>ric</u> t II			WELL API NO. 30-039-27284
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No. E-347-49
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			 Lease Name or Unit Agreement Name San Juan 30-6 Unit
1. Type of Well: Oil Well \Box Gas Well \boxtimes Other P&A			8. Well Number 443S
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289			10. Pool name or Wildcat Basin Fruitland Coal
4. Well Location			
Unit Letter O : 111		line and 139	
Section 36 Township 30N Range 6W NMPM Rio Arriba County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6727' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	SUB REMEDIAL WORI COMMENCE DRI CASING/CEMENT	LLING OPNS. 🗍 PANDA 🛛 🛛
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RCVD DEC 31 '12			
The subject well was P&A'd on $12/12/12$ per the attached report.			OIL CONS. DIV.
Approved for plugging of wellbore only. Liability under bond is retained pending Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web page			
Spud Date:	Rig und	er forms. w.emnrd.state.us/ocd	
DN	IB ())	w.eniniu.state.us/ood	
I hereby certify that the information	above is true and complete to the b	est of my knowledge	e and belief.
signature Allie	f Suge_TITLE_	<u>Staff Regulatory</u>	
Type or print name Dollie L. Busse E-mail address:dollie.l.busse@conocophillips.com _PHONE: 505-324-6104			
For State Use Only			
APPROVED BY:	D TITLE	eputy Oil & Ga Distric	
Conditions of Approval (if any):			DATE <u>VATIO</u> .
continuone or reprovar (n any).	Ŕv		

.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources San Juan 30-6 Unit 443 S

December 12, 2012 Page 1 of 1

1110' FSL and 1390' FEL, Section 36, T-30-N, R-6-W Rio Arriba County, NM Lease Number: E-347-49 API #30-039-27284

Plug and Abandonment Report Notified NMOCD and BLM on 12/6/12

Plug and Abandonment Summary:

Plug #1 with 29 sxs (34.22 cf) Class B cement inside casing from 3383' to 3232' to cover the Fruitland Coal top.

- **Plug #2** with 51 sxs (60.18 cf) Class B cement inside casing from 3006' to 2741' to cover the Kirtland and Ojo Alamo top.
- Plug #3 with 30 sxs (35.40 cf) Class B cement inside casing from 1750' to 1594' to cover the Nacimiento top.
- **Plug #4** with 48 sxs (56.64 cf) Class B cement inside casing from 193' to surface squeeze 8 sxs to cover the surface casing shoe.
- Plug #5 with 48 sxs (56.64 cf) Class B cement found cement down 5' in 7" casing and install P&A marker.

Plugging Work Details:

- 12/7/12 Road rig and equipment to location. Check well pressures: tubing 0 PSI, casing 90 PSI and bradenhead 0 PSI. RU flow lines open well to pit and blow down casing to 0 PSI. RU rod tools. PU on rod string to 20K and attempt to unseat pump by jarring rods. Unable to unseat work string to 28K with 22K over string rods, freed up. LD 1-22' polish rod, 20' ³/₄" pony rods, 138 ³/₄" plain rods, 16' pony rods, 6 K-bars, shear at shear coupling. SI well. SDFD.
- 12/10/12 Check well pressures: tubing 0 PSI, casing 90 PSI and bradenhead 0 PSI. Bled down to 0 PSI. ND wellhead. NU BOP. Pressure test BOP at 400 PSI and 1200 PSI, OK. PU on 2-3/8" production string, LD tubing hanger. TOH with 23 joints tubing to wet string. RIH with 1-9/10" tubing circulate shots and perf holes at 2765'. POH. TOH and tally 117 joints tubing. LD pump stack in profile nipple. 1-6', 10' sub with mud anchor. Total tubing length 3647.83'. RIH with 7" GR to 3400' POH. PU 1-7" DHS CR. TIH and set CR at 3375'. Pressure test tubing to 1000 PSI, bled down to 0 PSI in 10 minutes. Circulate well clean. Pressure test casing to 800 PSI, bled down to 0 PSI in 15 minutes, OK. TOH. SI well. SDFD.
- 12/11/12 Open up well; no pressures. Pressure test to 300 PSI for 10 minutes, OK. RU Basin Wireline. Ran CBL from 3383' to surface. Found cement at 40'. TIH open-ended to 3383'. Spot plug #1, #2, #3 and #4. LD all tubing. ND BOP. NU wellhead. SI well. SDFD.
- 12/12/12 Open up well; no pressures. Dig out wellhead. Fill out Hot Work Permit and cut off wellhead. Found cement down 5' in 7" casing. Spot plug #5 and install P&A marker. RD & MOL.

Robert Bixler, COPC representative, was on location. John Durham, BLM representative, was on location.