

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR JAN 18 201

FORM APPROVED OMB No. 1004-0137

BUREAU OF LAND MANAGEMENT Expires: July 31, 2010 Farmington Field (Structure Serial No. SF-07883 078885 SUNDRY NOTICES AND REPORTS ดีเก็ติย์เน้ร and Mana 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Canyon Largo Unit Oil Well X Gas Well 8. Well Name and No. Other Canyon Largo Unit #239 2. Name of Operator . 9. API Well No. 25633 **Burlington Resources Oil & Gas Company LP** 30-039-20129-3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 Blanco Mesaverde 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Surface Unit K, 1550' FSL & 1600' FWL, Sec. 1, T25N, R6W, NMMP Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Water Shut-Off Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Plans are to recomplete this well in the Mesaverde formation and then DHC the existing Dakota with the Mesaverde. Attached is the MV plat and procedure. The DHC application will be submitted and approved before the work proceeds. Provide CBL & MIT result prior to commen recompletion operations. RCVD JAN 31'13 ATL COMS. DIV. DIST. 3 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Sr. Regulatory Specialsit **Patsy Clugston** Title 1/18/2013 Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Office that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any

Title

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Approved by

<u>District 1</u>
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
<u>District 11</u>
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District 111

1000 Rio Brazos Rd., Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 District IV

1220 S, St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 Form C-102 August 1, 2011

Permit 159613' 775

JAN 18 2013

Farmington Field Office

WELL LOCATION AND ACREAGE DEDICATION PLATFICAU of Land Management

1. API Number	2. Pool Code	I Name			
30–039–20639	72319	DE (PRORATED GAS)			
4. Property Code	,	rty Name	6. Well No.		
6886		ARGO UNIT	239		
7. OGRID No.	8. Opera	9, Elevation			
14538	BURLINGTON RESOURCE	6740			


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet Prom	N/S Line	Feet From	E/W Line	County
įΚ	1	25N	06W		1550	S	1600	W	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

U	II Lot	Section	Township	Range	1.ot	ldn	Feet From	N/S L	ine	Feet From	E/W Line	County
	12. Dedicated Acres 320.60 W/2			Joint or Infill	14		4. Consolidation Code		15. Order No.			

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Must number Title: Regulatory Technician Date: 12/18/12

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By: David Kilven Date of Survey: 4/23/\$973 Certificate Number: 1760

Canyon Largo Unit 239

Section 1, Township 25N, Range 6W
API# 3003920639

MV Recompletion Sundry

12/13/2012

Procedure:

- 1. MIRU service rig. TOOH with current production tubing string.
- 2. Wireline set a 4-1/2" composite bridge plug in the casing above the existing Dakota perforations.
- 3. Run a GR/CCL/CBL correlation log under 1000 psi. The GR will be used to pick formation tops and the CBL will be used to pick the TOC. Logs will be used to determine the need for remedial cement work.
- 4. Perforate the first stage Mesaverde (Point Look out).
- 5. Fracture stimulate first stage Mesaverde.
- 6. RIH and set a composite frac plug above the first stage Mesaverde.
- 7. Perforate the second stage Mesaverde (Menefee).
- 8. Fracture stimulate the second stage Mesaverde.
- 9. Flow back fracs on clean-up into steel pit. RIH and wireline set a composite bridge plug 50ft above top perf.
- TIH with a mill and drill out top two composite plugs. Clean out to bottom composite plug below entire Measverede.
- 11. Flow test Mesaverde up casing.
- 12. TIH with a mill and drill out bottom composite plug and cleanout to PBTD. TOOH.
- 13. TIH and land production tubing. Get a commingled Dakota / Mesaverde flowrate.
- 14. Release service rig and turn well over to production.