

Submit 3 Copies To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Ave., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Jun 19, 2008

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. <b>30-045-31444</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. FEE
7. Lease Name or Unit Agreement Name <b>Maddox Waller</b>
8. Well Number <b>101S</b>
9. OGRID Number <b>14538</b>
10. Pool name or Wildcat <b>Basin Fruitland Coal</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other **P&A**

2. Name of Operator  
**ConocoPhillips Company**

3. Address of Operator  
P.O. Box 4289, Farmington, NM 87499-4289

4. Well Location  
 Unit Letter **C** : **855** feet from the **North** line and **1420** feet from the **West** line  
 Section **14** Township **32N** Range **11W** NMPM **San Juan County**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
6392' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<p><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/></p> <p>DOWNHOLE COMMINGLE <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p><b>SUBSEQUENT REPORT OF:</b></p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/></p> <p>CASING/CEMENT JOB <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>
--	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The subject well was P&A'd on 6/4/13 per the attached report.

RCVD JUN 26 '13  
 OIL CONS. DIV.  
 DIST. 3

Spud Date:  Rig Released Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Dollie L. Busse* TITLE Staff Regulatory Technician DATE 6/25/13

Type or print name Dollie L. Busse E-mail address: dollie.l.busse@conocophillips.com PHONE: 505-324-6104

**For State Use Only**

APPROVED BY: *Bob Bell* TITLE Deputy Oil & Gas Inspector, District #3 DATE 7/5/13  
 Conditions of Approval (if any): A

Approved for plugging of wellbore only.  
 Liability under bond is retained pending.  
 Receipt of C-103 (Subsequent Report of Well Plugging) which may be found @ OCD web page under forms  
 www.emnrd.state.us/ocd

# A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 \*fax: 505-325-1211

Burlington Resources  
**Maddox Waller 101S**

June 4, 2013  
Page 1 of 1

855' FNL and 1420' FWL, Section 14, T-32-N, R-11-W  
San Juan County, NM  
Lease Number: Fee  
API #30-045-31444

**Plug and Abandonment Report**  
Notified NMOCD and BLM on 5/29/13

## Plug and Abandonment Summary:

- Plug #1** with CR at 2738' spot 40 sxs (47.2 cf) Class B cement inside casing from 2738' to 2531' to cover the Intermediate Casing Shoe and Fruitland top.
- Plug #2** with 40 sxs (47.2 cf) Class B cement inside casing from 1287' to 1085' to cover the Kirtland and Ojo Alamo tops.
- Plug #3** with 49 sxs (57.82 cf) Class B cement inside casing from 187' to surface to cover the surface casing shoe.
- Plug #4** with 44 sxs Class B cement found cement at surface and install P&A marker.

## Plugging Work Details:

- 5/30/13 Rode rig and equipment to location. LO/TO. Spot in tight location. Check well pressures: casing 60 PSI, tubing and bradenhead 0 PSI. Dig out and plumb in bradenhead valve. SDFD.
- 5/31/13 Open up well; no pressures. X-over to rod equipment. Pressure test tubing to 1000 PSI, OK. LD polish rod, 115 3/4" rods, 2-8' pony rods, 6 - K-bars, 1-6' guided rod, x-over to tubing equipment. ND wellhead and NU BOP. Pressure test BOP to 1000 PSI bled down to 250 PSI. Pressure test bradenhead to 300 PSI, OK. Tally and TOH 8 EUE, 98 joints, 1-10' pup, 1-4' pup, FN and mud anchor – cut mule shoe total 3068'. TIH and tag TOC at 2765'. TIH with 7" DHS CR and set 2738'. Circulate well clean. Pressure test casing to 800 PSI, OK. Open casing valve and bled pressure off. RU Blue Jet wireline. Ran CBL, called TOC at 60'. SI well. SDFD.
- 6/3/13 Open up well; no pressures. Pressure test casing to 800 PSI, OK. Establish circulation. Spot plug #1, #2 and #3. Dig out wellhead. SI well. SDFD.
- 6/4/13 Open up well; no pressures. RU High Desert and perform Hot Work Permit. Found cement at surface. Spot plug #4 and install P&A marker. RD and MOL.

Vic Montoya, MVCI representative, was on location.

Monica Kuehling, NMOCD representative, was on location.