

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Hardie LS 5B	Facility Type: Natural Gas Well
Surface Owner: Federal	Mineral Owner: Federal
API No.: 3004529714	

LOCATION OF RELEASE


Unit Letter L	Section 23	Township 29N	Range 08W	Feet from the 2530	North/South Line South	Feet from the 1160	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.71079 Longitude -107.65058

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 206 MCF	Volume Recovered: none
Source of Release: hung dump valve	Date and Hour of Occurrence: 8/24 1:00 am - 8/26 8:00 am	Date and Hour of Discovery: 8/26 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	RCVD SEP 17 '13
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV. DIST. 3	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Field technician arrived on location to start compressor and found dump on separator hung open and blowing to BGT. Dump valve was found to be out of adjustment. Operation specialist and technician corrected problem and are monitoring to ensure problem is fixed.		
Describe Area Affected and Cleanup Action Taken.* Natural gas dissipated to atmosphere, so no clean-up action is possible.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Field Environmental Advisor	Approval Date: <u>10/23/2013</u>	Expiration Date:
E-mail Address: <u>Courtney.Cochran@bp.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/04/13	Phone: 505-326-9457	

* Attach Additional Sheets If Necessary

njk 1329653706