

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: San Juan 29-5 48C	Facility Type: Gas Well

Surface Owner Public	Mineral Owner Fee	API No. 3003929693
-----------------------------	-------------------	---------------------------

LOCATION OF RELEASE

Unit Letter C	Section 15	Township 29N	Range 05W	Feet from the 805'	North/South Line FNL	Feet from the 1720'	East/West Line FWL	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	--------------------------------	-------------------------------	------------------------------	-----------------------------

Latitude **36.73058** Longitude **-107.34723**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40 BBLS	Volume Recovered 40 BBLS
Source of Release BGT	Date and Hour of Occurrence 2/14/14 unknown time	Date and Hour of Discovery 2/14/14 8AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell & Jonathon Kelly	
By Whom? Lisa Hunter	Date and Hour 2/14/14 2:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD FEB 19 '14
OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Water hauler discovered the overflow upon arriving on location. 40.3 bbls of produced water (conventional) had overflowed into the cribbing - 40 bbls of fluid was recovered. The release was contained and did not leave location.

Describe Area Affected and Cleanup Action Taken.*
ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 4/28/14	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/17/14 Phone: (505) 599-4089		

* Attach Additional Sheets If Necessary

NCS 141 184 2417