s de	Submit 'l Copy To Appropriate District Office	State of New Mexico			Form C-103				
	District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.					
	1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH CONCEDUA			30-045-28693				
	811 S. First St., Artesia, NM 88210 District III – (505) 334-6178		OIL CONSERVATION DIVISION			Type of Lease			
	1000 Rio Brazos Rd., Aztec, NM 87410		1220 South St. Francis Dr. Santa Fe, NM 87505		STA				
	<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Salita Pe, INIVI 87303			6. State Oil & Gas Lease No. E-4777 - L-4693 - B-9590				
Г	87505	SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name			
	(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO	A	7. Lease Na	inte of Olit Agreement	Name		
	DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C	C-101) FOR SUCH		Buena Sue				
	1. Type of Well: Oil Well	Gas Well Other			8. Well Number 1				
	2. Name of Operator	UI	L CONS. DIV DIS	T. 3	9. OGRID	Number			
ŀ	Elm Ridge Exploration Co LLC 3. Address of Operator	NOV 0 5 2014			149052 10. Pool name or Wildcat				
	PO BOX 156 Bloomfield, NM 874	113	140 4 6 9 2014		Basin Fruit				
t	4. Well Location					· · · · · · · · · · · · · · · · · · ·			
	Unit LetterG_:1830	feet from theNort	h_ line and2130'	feet fro	om the _East	line			
L	Section 32	Township 26N	Range 11W		NMPM	San Juan County			
	2	11. Elevation (Show wheth 6245)	her DR, RKB, RT, G	R, etc.)		7	\$4.		
L		0243							
	12. Check A	Appropriate Box to Indi	cate Nature of No	otice. I	Report or C	ther Data			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data									
	NOTICE OF IN PERFORM REMEDIAL WORK □		REMEDIAL			REPORT OF:	NC \square		
	TEMPORARILY ABANDON		-		.LING OPNS.				
	PULL OR ALTER CASING		CASING/C						
	DOWNHOLE COMMINGLE								
	CLOSED-LOOP SYSTEM	1	- OTHER				_		
-	OTHER: 13 Describe proposed or comp	leted operations (Clearly st	OTHER:	ails and	give nertiner	nt dates, including estim	ated date		
	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
	proposed completion or recompletion.								
F	Elm Ridge Exploration Co LLC re	quest permission to Plug a	nd Abandon the al	bove we	ell per the at	tached procedure.			
	Notify NMOC								
prior to beg operation									
		•	•						
		· · · · · · · · · · · · · · · · · · ·							
S	pud Date: 9-24-92	Rig Rel	ease Date:						
		1							
Ī	hereby certify that the information	alove is true and complete to	o the best of my kno	wledge	and belief.				
	X .	/							
S	IGNATURE /	TITLE	Sr. Regulatory	Supervi	sor DAT	TE08-20-14			
							,		
	Type or print nameAmy Archul For State Use Only	eta E-mail address:	aarchuleta@eln	nridge.ı	net	PHONE: _505-632-347	6		
r	or State Use Omy	711	Paragraph on a sa-	(B			ſ		
	APPROVED BY: The first	TITLE_	CEPUTY OIL & GAS	IMSPEC	TOR. Dist 🎄	_DATE	1		
C	Conditions of Approval (if any):	-							

Elm Ridge Resources

Pertinent Data Sheet

Well Name:

Buena Suerte 32G Com #1

Footage:

1830' FNL and 2130' FEL

Location:

SWNE Section 32, T26N, R11W

County:

San Juan County, NM

API#:

30-045-28693

Field:

Basin Fruitland Coal

Elevation: 6258' KB

TD: 1415' KB

PBTD: 1363 KB

Completed: 10/12/1992

Casing Record:

Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
8-3/4"	7"	20#	J-55	130'	70.8 cu. ft. (Circ. to surface)
6-1/4"	4-1/2"	9.5#	J-55	1406'	252.5 cu. ft. (Circ. to surface)

Tubing: 1-1/2" tubing set at 1277'

Formation Tops:

Nacimiento

Surface

Fruitland

1154'

Pictured Cliffs

1307'


Perforations:

Fruitland perforations: 1273'-1295'

Notes:


Wellbore Diagram Buena Suerte 32G Com#1 SWNE Sec. 32, T26N, R11W San Juan County, NM API #30-045-28693

Before



Wellbore Diagram Buena Suerte 32G Com#1 SWNE Sec. 32, T26N, R11W San Juan County, NM API #30-045-28693

Before



Plugging Program for Bisti 32G Com #1

- 1) MOL RU. TOOH with 1-1/2" tubing.
- 2) PU and TIH with 4-1/2" retainer to 1270'. Squeeze below retainer with 8 sx cmt.
- 3) Sting out, mix and pump 100 sx, or sufficient volume, to bring cement to surface inside 4-1/2" casing.
- 4) Cut off well head 4 feet below surface and remediate location in accordance with regulatory agencies' conditions of approval.