

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

JAN 08 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Rev. 1/7/2015

Release Notification and Corrective Action

OPERATOR

X Initial Report

☐ Final Report

Name of Company: Encana Oil & Gas (USA), Inc	Contact: Tucker Smith	
Address: 6584 E Main St., Farmington, NM 87402	Telephone No.: 505-599-2407	
Facility Name: Lybrook 102 2308 01H	Facility Type: E&P Production	
Surface Owner: State Lands	Mineral Owner: State Lands & BLM (comingled)	API No. 30-045-35365

LOCATION OF RELEASE

Unit Letter I	Section 2	Township 23N	Range 8W	Feet from the 2298'	North/South Line South	Feet from the 723'	East/West Line East	County San Juan
------------------	--------------	-----------------	-------------	------------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude 36.25519 N Longitude 107.64465 W - NAD83

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 6 bbl	Volume Recovered: 6 bbl
Source of Release: Pump freeze / float freeze at Combustor	Date and Hour of Occurrence: 1/2/2015, 06:00	Date and Hour of Discovery 1/2/2015, 06:00
Was Immediate Notice Given? <input type="checkbox"/> Yes X No X Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

During the early morning of January 2, 2015, freezing temperatures caused a float within a pump to freeze, allowing for approx. 6 bbls of oil to be released from the combustor vents on the Lybrook 102 2308 01H well location.

Describe Area Affected and Cleanup Action Taken.*

All released fluids were confined to the location boundaries. Vac truck collected all standing fluids. Equipment was used to scrape all affected material from frozen terrain.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tucker Smith 	OIL CONSERVATION DIVISION	
Printed Name: Tucker Smith	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 2/6/15	Expiration Date:
E-mail Address: tucker.smith@encana.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/5/2015 Phone: 505-599-2407	Soil Samples Required For Closure # NCS 1503741750	

* Attach Additional Sheets If Necessary

①