Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
District #- (575) 393-6161	Energy, Minerals and Natural Resource	es Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283		WELL API NO. 30-045-28742
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	F I I' . T CI
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 8741	1220 South St. Francis Dr.	STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87 59 5	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	CONS	314624
SUNDRY N (DO NOT USE THIS FORM FOR PR DIFFERENT RESERVOIR. USE "AI	OTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BUG TO A PPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 314624 7. Lease Name or Unit Agreement Name MCCARTHY 29-9-30 8. Well Number #1
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number #1
2. Name of Operator SOUTHLAND ROYALT		9. OGRID Number 370292
3. Address of Operator	T COMPANY LLC	10. Pool name or Wildcat
400 WEST 7th STREET	, FORT WORTH, TX 76102	To. Tool name of Wildean
4. Well Location Unit Letter B: 1065 1065		
Section 30	Township 29N Range 09W	NMPM County SAN JUAN
	11. Elevation (Show whether DR. RKB, RT, G	P atc.)
11. Elevation (snow whether DR, RRB, RT, GR, etc.) 5701'		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	The state of the s	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING	☐ MULTIPLE COMPL ☐ CASING/C	EMENT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM OTHER:	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Procedure to repair leaks in the 5 1/2" production casing; return well to production on rod pump:		
1. Set RBP at 1,100', dump sand on top of plug. Use packer to isolate exact locations of casing leaks in the		
5-1/2" production casing (~700-900').		
2. Establish rate if possible into leaks. If injection cannot be established, shoot squeeze holes into the leaking		
intervals so that rate can be established. (Original CBL shows cement bond up into surface pipe.)		
Circulate cement above the leaks and squeeze at ~1,000 psi. If injection cannot be established, spot cement across from intervals and squeeze/hesitate. Drill out and test to 500 psi for 30 minutes. Return the well to		
production on beam pump.		
Spud Date: 11/02/1992	Rig Release Date: 11/9	03/1992
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
34.110-		
SIGNATURE TITLE Regulatory Compliance DATE 8/14/2015		
Type or print name Robbie Grigg E-mail address: rgrigg@mspartners.con PHONE: 817-334-7842		
For State Use Only		
CUPERVISOR DISTRICT #3 AUG 2 1 2015		
APPROVED BY: (Mart 1 - TITLE DATE DATE Conditions of Approval (if any):		

McCarthy 29-9 30-1 FC API: 30-045-28742 Last Update: 5/6/2014



ELEV: KB 5,714' GL 5,701' **CORR 13'**

Weatherford 57-109-48

121/4" HOLE

85/8", 23#, X42LS, STC CSG @ 2651. Cmt'd w/200 SX CL "B" CMT & 2% CaCl2 (236 ft3). Circ 10sx cmt to surface.

7 7/8" HOLE

5.5", 15.5#, J-55 CSG. Guide shoe @ 2,249'. FC @ 2206'. LEAD: Cmt'd w/300 SX Pacesetter Lite w/ 6% gel (579 ft3). TAIL: 100 SX CL "B" w/1% CF-14 & 0.4% ThriftyLite (119 ft3). Circ. no cmt to surface.

TBG: 14 10' MA, 8'PS, SN, 67 jts 2 3/8" J-55 tbg, Landed tbg SN @ 2098.06' KB EOT @ 2120 27' KB

RODS. 4 - 25' 1.25" Kbars, 78- 3/4" rods, 8'-4'-2'- 3/4" pony, 11/4" x22' Polished rod.

PUMP. 2" x 11/4" x 6' x 7' x 10' RHAC-HVR pump 42" stroke

Perf's: 1924'-40', 1962'-75', 2040'-53' 4spf, 168 holes, 0.45" dia

Frac 02/25/1993

Total proppant 125,000 lbs Total load 3390 bbls

ATR = 75 bpm @ 1100 psi

PBTD: 2,170' TD: 2,253'