

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
GSA # 1004-0135
Expires January 31, 2004

5. Lease Serial No.	36096
6. If Indian, Allottee or Tribe Name	NA
7. If Unit or C/V Agreement, Name and/or No.	
8. Well Name and No.	San Isidro 12-2
9. API Well No.	30-043 -20721
10. Field and Pool, or Exploratory Area	Rio Puerco
11. County or Parish, State	Sandoval County, NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Pride Energy Company	
3a. Address P.O. Box 701950, Tulsa, OK 74170	3b. Phone No. (include area code) (918) 524-9200
4. Location of Well (Footage, Sec., T. R., M., or Survey Description) Unit Letter B: 1,980' FEL and 660' FNL of Section 12-20N-3W	

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Drill up CIBP @ 4,290'

Clean out wellbore to PBTD @ 4503'

Treat Gallup from 4115' to 4340' with 155 gals. of Xylene & 1500 gals. of 15% HCL

Estimated start date: Sometime between 10/27/05 & 11/3/05

Estimated duration of workover: 4 days To be completed by 12/31/05

Bond#: BD 101035



14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

By: Pride Production Co., Inc.
Title: General Partner
By: Matthew L. Pride Energy Company
Title: President

Signature

Matthew L. Pride

Title

Date

10/20/05

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by **Original Signed: Stephen Mason**

Title

Date

OCT 24 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOC