Submit 3 Copies 10 Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-045-33042
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV Santa Fe, NM \$7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	E-3071-2
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLANS BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM CANDES OF SUICH)	
PROPOSALS.)	San Juan 32-9 Unit 8. Well Number
1. Type of Well: Oil Well Gas Well Other Of Gas Well	#217S
2. Name of Operator	9. OGRID Number
Burlington Resources Oil & Gas Company LP	14538
3. Address of Operator 3401 E. 30 th Street, Farmington, NM 87402	10. Pool name or Wildcat Basin Fruitland Coal-71629
5401 E. 50 Succe, 1 animington, 1411 67402	Basin Fluidand Coal-/1029
4. Well Location	
Unit Letter I: 1625 feet from the South line and 660	feet from the East line
Section 16 Township 32N Range 9W NMPM	County San Juan
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure	
	ance from nearest surface water
	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	
	Report of Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORI	
TEMPORARIL VARIANDON TO CHANCE DI ANC	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	LLING OPNS. P AND A
TEMPORARILY ABANDON	LLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	LLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	LLING OPNS. P AND A JOB 2" Liner & Completion detail digive pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: 5-1/	LLING OPNS. P AND A JOB 2" Liner & Completion detail digive pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.	LLING OPNS. P AND A 7 JOB 2" Liner & Completion detail d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150	P AND A T JOB 2" Liner & Completion detail di give pertinent dates, including estimated date tach wellbore diagram of proposed completion OO PSI/ 30 min. ok. RIH tagged cmnt. @
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist, drill open hole to the starting and the	LLING OPNS. ☐ P AND A ☐ 2" Liner & Completion detail ☑ d give pertinent dates, including estimated date tach wellbore diagram of proposed completion 00 PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist. D/O to shoe, 3402'. Circ. w/ air & mist, drill open hole to on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear	LLING OPNS. ☐ P AND A ☐ 2" Liner & Completion detail ☑ d give pertinent dates, including estimated date tach wellbore diagram of proposed completion 00 PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural &
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist. D/O to shoe, 3402'. Circ. w/ air & mist, drill open hole to on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear energized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 5	P AND A 2" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion O PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 6-1/2" 15.5#, J-55 LT&C liner & set @
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist, drill open hole to on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear energized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 53801' w/ TOL @ 3375' (18' overlap). Liner is a pre-perf'd liner @ 1spf, perfs from	LLING OPNS. P AND A 2" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion O PSI/ 30 min. ok. RIH tagged cmnt. from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 5-1/2" 15.5#, J-55 LT&C liner & set @ 13420' − 3527', 3570' − 3592',
PULL OR ALTER CASING	Z" Liner & Completion detail 2" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion OO PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 6-1/2" 15.5#, J-55 LT&C liner & set @ 13420' - 3527', 3570' - 3592', 8" 4.7# J-55 tubing (123 jts) & landed @
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist. D/O to shoe, 3402'. Circ. w/ air & mist, drill open hole to on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear energized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 53801' w/ TOL @ 3375' (18' overlap). Liner is a pre-perf'd liner @ 1spf, perfs from 3634' – 3656', 3698' – 3720' =173 holes. Circ. w/ air, mist, & foamer. RIH w/ 2-3/	Z" Liner & Completion detail 2" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion OO PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 6-1/2" 15.5#, J-55 LT&C liner & set @ 13420' - 3527', 3570' - 3592', (8" 4.7# J-55 tubing (123 jts) & landed @
PULL OR ALTER CASING	Z" Liner & Completion detail 2" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion OO PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 6-1/2" 15.5#, J-55 LT&C liner & set @ 13420' - 3527', 3570' - 3592', (8" 4.7# J-55 tubing (123 jts) & landed @
PULL OR ALTER CASING	Z" Liner & Completion detail 2" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion OO PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 6-1/2" 15.5#, J-55 LT&C liner & set @ 13420' - 3527', 3570' - 3592', 8" 4.7# J-55 tubing (123 jts) & landed @
PULL OR ALTER CASING	2" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion O PSI/ 30 min. ok. RIH tagged cmnt. from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 5-1/2" 15.5#, J-55 LT&C liner & set 1 3420' − 3527', 3570' − 3592', 8" 4.7# J-55 tubing (123 jts) & landed @ g, test tbg & pump w/ 1000 PSI- ok.
PULL OR ALTER CASING MULTIPLE COMPL OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist. D/O to shoe, 3402'. Circ. w/ air & mist, drill open hole to on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear energized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 53801' w/ TOL @ 3375' (18' overlap). Liner is a pre-perf'd liner @ 1spf, perfs from 3634' – 3656', 3698' – 3720' =173 holes. Circ. w/ air, mist, & foamer. RIH w/ 2-3/3760' w/ SN @ 3735'. ND BOP, NU WH, rig up for rods, spaced out pump, fill the	2" Liner & Completion detail \(\square\) digive pertinent dates, including estimated date tach wellbore diagram of proposed completion \(\text{DO PSI} \) 30 min. ok. RIH tagged cmnt. \(\text{@ from 3406' to 3801' (TD)}. \(\text{TD reached an w/ air, mist & foamer, cont. natural & 5-1/2" 15.5#, J-55 LT&C liner & set \(\text{@ 13420'} - 3527', 3570' - 3592', \) (8" 4.7# J-55 tubing (123 jts) & landed \(\text{@ 23} \) g, test tbg & pump w/ 1000 PSI- ok.
OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist. D/O to shoe, 3402'. Circ. w/ air & mist, drill open hole to on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear energized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 53801' w/ TOL @ 3375' (18' overlap). Liner is a pre-perf'd liner @ 1spf, perfs from 3634' − 3656', 3698' − 3720' =173 holes. Circ. w/ air, mist, & foamer. RIH w/ 2-3, 3760' w/ SN @ 3735'. ND BOP, NU WH, rig up for rods, spaced out pump, fill the RD & released rig 11/11/05. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □	P AND A 2" Liner & Completion detail di give pertinent dates, including estimated date tach wellbore diagram of proposed completion O PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached an w/ air, mist & foamer, cont. natural & 5-1/2" 15.5#, J-55 LT&C liner & set @ 1 3420' − 3527', 3570' − 3592', 8" 4.7# J-55 tubing (123 jts) & landed @ g, test tbg & pump w/ 1000 PSI- ok. e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan □.
PULL OR ALTER CASING	Z" Liner & Completion detail di give pertinent dates, including estimated date tach wellbore diagram of proposed completion O PSI/ 30 min. ok. RIH tagged cmnt. from 3406' to 3801' (TD). TD reached mw/air, mist & foamer, cont. natural & 5-1/2" 15.5#, J-55 LT&C liner & set 1 3420' - 3527', 3570' - 3592', 1 3420' - 3527', 3570' - 3592', 2 34.7# J-55 tubing (123 jts) & landed 2 35, test tbg & pump w/ 1000 PSI- ok.
OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 3357'. Circ. w/ air & mist. D/O to shoe, 3402'. Circ. w/ air & mist, drill open hole to on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear energized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 53801' w/ TOL @ 3375' (18' overlap). Liner is a pre-perf'd liner @ 1spf, perfs from 3634' − 3656', 3698' − 3720' =173 holes. Circ. w/ air, mist, & foamer. RIH w/ 2-3, 3760' w/ SN @ 3735'. ND BOP, NU WH, rig up for rods, spaced out pump, fill the RD & released rig 11/11/05. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □	Z" Liner & Completion detail digive pertinent dates, including estimated date tach wellbore diagram of proposed completion OO PSI/ 30 min. ok. RIH tagged cmnt. @ from 3406' to 3801' (TD). TD reached in w/ air, mist & foamer, cont. natural & 6-1/2" 15.5#, J-55 LT&C liner & set @ 13420' - 3527', 3570' - 3592', (8" 4.7# J-55 tubing (123 jts) & landed @ 123, test tbg & pump w/ 1000 PSI- ok.
OTHER: OTHER: OTHER: OTHER: OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 (3357'. Circ. w/ air & mist. D/O to shoe, 3402'. Circ. w/ air & mist, drill open hole on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole clear energized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 53801' w/ TOL @ 3375' (18' overlap). Liner is a pre-perf'd liner @ 1spf, perfs from 3634' - 3656', 3698' - 3720' =173 holes. Circ. w/ air, mist, & foamer. RIH w/ 2-3/3760' w/ SN @ 3735'. ND BOP, NU WH, rig up for rods, spaced out pump, fill the RD & released rig 11/11/05. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines \(\), a general permit \(\) SIGNATURE TITLE Regulatory Associate I Type or print name Philana Thompson E-mail address: PThompson@br-inc.com For State Use Only	LLING OPNS. PAND A DIT JOB DIT
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: 5-1/ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/17/05 MIRU Aztec #376. ND WH, NU BOP. PT csg & blind rams press. to 150 (3357°. Circ. w/ air & mist. D/O to shoe, 3402°. Circ. w/ air & mist, drill open hole on 10/20/05. SI for PSI build, energized & natural surges for 2 days. Circ. hole cleatenergized surges for 8 days, circ, & C/O w/ air mist, and foamer. 11/9/05 RIH w/ 5301° w/ TOL @ 3375° (18° overlap). Liner is a pre-perf'd liner @ 1spf, perfs from 3634° – 3656°, 3698° – 3720° =173 holes. Circ. w/ air, mist, & foamer. RIH w/ 2-3/3760° w/ SN @ 3735°. ND BOP, NU WH, rig up for rods, spaced out pump, fill the RD & released rig 11/11/05. I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE TITLE Regulatory Associate I Type or print name Philana Thompson E-mail address: PThompson@br-inc.com	LLING OPNS. PAND A DISTRICT PORT OF JOB PAND A DISTRICT PORT OF JOB DISTRICT PORT OF JOB DISTRICT PORT OF JOB DISTRICT PORT OF JOB DE L'ALLE PAND A