In Lieu of Form 3160 (June 1990)

X Subsequent Report

Final Abandonment

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED					
Budget Bureau No. 1004-0135					
Expires: March 31, 1993					

SLINDRY NOTICE AND REPORTS ON WI	G1 1	1 (2

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

 Lease Designation and Serial No. SF-078892

Non-Routine Fracturing

Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and

Water Shut-Off

Dispose Water

dm

		(100	I UEG Z I	P. <u>.i</u>	U D Indian, Allottee or Tribe Name
	SUBMIT IN 1	TRIPLICATE (RECEN 170 FARMIN	ED GTON	If Unit or CA, Agreement Designation
i.	Type of Well Oil Well X Gas Well Other	Q 10 11 12	374753	8.	Well Name and No. ROSA UNIT #104
2.	Name of Operator WILLIAMS PRODUCTION COMPANY	TO THE STATE OF	37.18	9.	API Well No. 30-039-23530
3.	Address and Telephone No. PO BOX 3102 MS 25-1, TULSA, OK 74101	(918) 573-6254	373777	10.	Field and Pool, or Exploratory Area
4.	Location of Well (Footage, Sec., T., R., M., or 1820' FNL & 1210' FEL, SE/4 NE/4 SEC 14-			11.	County or Parish, State RIO ARRIBA, NM
	CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE	COF NOTICE, REP	ORT, OR	OTHER DATA
	TYPE OF SUBMISSION		TYPE	OF ACTIO)N
	Notice of Intent	X Abandonment Recompletion			Change of Plans New Construction

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Back Casing Repair

Altering Casing

Other

10-24-2005 MIRU, check psi on well. Csg, tbg & bradenhead – 0#. TIH, tag ret @ 7325'. Load & circulate hole clean with 130 bbls water. Plug #1 – mix & pump 41 sxs (54.1 cu.ft) Type III cmt from 7325' to TOC @ 6705'. Test csg to 600#, held for 5 min OK. LD tbg to 6529', POOH 10 stds to 5892', SDFN.

10-25-2005 TIH w/ tbg to 6497' & tag TOC. Load hole w/ 2.5 bbls water. Plug #2 – mix & pump 60 sxs (79.2 cu.ft.) Type III cmt from 6497' to TOC @ 5590'. Load hole with 5 bbls water. Plug #3 – mix & pump 53 sxs (69.9 cu.ft.) Type III cmt from 3726' to TOC @ 2924'. LD tbg to 1977'. Load hole with 3 bbls water. Plug #4 – mix & pump 24 sxs (31.6 cu.ft.) Type III cmt from 1977' to TOC @ 1614'. LD remaining tbg. RU wireline, TiH & perf 3 holes @ 464', POOH. RD wireline. Load hole with 3.5 bbls water. Pump into perfs @ 464' @ 1.5 bpm @ 700#, no blow out-thru-the bradenhead. Pump .5 bbl down the bradenhead & pressured up & held @ 600#. PU 17 jts of tbg to 541', break circulation out the csg with 1 bbl water. Plug #5 – mix & pump 43 sxs (57.1 cu.ft.) Type III cmt from 541' with good cmt returns out the csg. LD all tbg, wash up tbg equipment & BOP. SDFN.

10-26-2005 PU 2 jts, tag TOC @ 60', LD 2 jts, ND BOP. Dig out & cut off wellhead, install-marker with 20 sxs cmt (5 sxs to top off 4 ½" csg & 15 sxs for marker. Well P&A'd @ 1200 hrs 10/26/05. Cut off anchors, release rig @ 1200 hrs, 10/26/05.

14.	I hereby certify that the foregoing is true and correct Signed Tracy Ross	Title Production Analyst	Date	December 1, 2005
	(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title		Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United Statements or representations as to any matter within its jurisdiction.



DEC 0 5 2005

