Form 3160-5 (September 2001)

D B

UNITED STATES	
DEPARTMENT OF THE INTERIOR	
BUREAU OF LAND MANAGEMENT	

	FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004
5.	Lease Serial No.
	NINGNING 101FF9

5.	Lease Serial No.
	NMNM-101552

SUNDRY	NMNM-101552								
Do not use th		Allettee or Tribe Name							
abandoned we	MA 1/2	747							
SUBMIT IN TRI	PLICATE- Other instr	uctions on	revers	e side. REC	7. If Unit or (CA/Agreement, Name and/or No.			
1. Type of Well Oil Well	Gas Well Other	070 FARM	8. Well Nam	ki ki					
2. Name of Operator			WF Fed	eral 1 #1					
2. Name of Operator Lance Oil & Gas Company, Inc.						9. API Well No. 30-045-30660			
3a. Address P. O. Box 70, Kirtland, NM 87417 3b. Phone No. (include area code) 505-598-5601						Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., 2			Hill PC/Basin Fruitland Coal						
Section 1, T30N-R14W	11. County o	r Parish, State							
1940' FSL & 1520' FWL					San Juan County, NM				
12. CHECK AF	PROPRIATE BOX(ES) TO	INDICATE 1	NATURE	OF NOTICE, RI	PORT, OR	OTHER DATA			
TYPE OF SUBMISSION	" 		TYPI	E OF ACTION					
	Acidize	Deepen		Production (Star	rt/Resume)	Water Shut-Off			
Notice of Intent	Alter Casing	Fracture Tre	at	Reclamation		Well Integrity			
Subsequent Report	Casing Repair	New Const		Recomplete	•	Other Cut Off & Bury			
Final Abandonment Notice	Change Plans Convert to Injection	Plug and At Plug Back	oandon	☐ Temporarily Aba ☐ Water Disposal	andon	Dry Hole Marker			
13. Describe Proposed or Complete				·					
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Operator Lance Oil & Gas Company Inc. proposes to cut off and bury the dry hole marker for Texaco's P&A'd Dick Hunt #2 that is situated on the well pad of Lance's WF Federal 1 #1 as follows: Dig down around the P&A marker approximately 4 foot. Cut off P&A marker post. Weld steel cap on the existing P&A stub. Re-attach the aluminum stamped sign to the weld cap from the old P&A Marker post. Bury stub. Cut P&A marker off @ ground level, then reweld if back in Place after completion of new well.									
14. I hereby certify that the fore Name (Printed/Typed)	going is true and correct		-			(a) (b)			
Jo Becksted			Title Co	mpliance Administ	rator				
Signature	relisted		Date	1	2/03/2004	VC 6 200			
V	THIS SPACE FOR	FEDERAL	OR ST	ATE OFFICE	USE	1 65 M			
Approved by Odul	Trus		Ti	te EPS		Detc 12/13/04			
Conditions of approval, if any, are certify that the applicant holds legal which would entitle the applicant to	l or equitable title to those rights i			fice		1 1-			
Title 18 U.S.C. Section 1001 and Titl States any false, fictitious or fraudu	e 43 U.S.C. Section 1212, make it a lent statements or representations	crime for any	person kno within its	wingly and willfully jurisdiction.	to make to any	department or agency of the United			

(Instructions on page 2)