New Mexico Energy Minerals and Natural Resources Department

Form C-140 Revised 06/99

<u>District I</u> - (505) 393-6161 1625 N. French Dr, Hobbs, NM 88240 <u>District II</u> - (505) 748-1283 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> - (505) 334-6178 1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

<u>District IV</u> - (505) 476-3440

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, New Mexico 87505 (505) 476-3440

SUBMIT ORIGINAL PLUS 2 COPIES TO APPROPRIATE DISTRICT OFFICE

APPLICATION FOR WELL WORKOVER PROJECT

I.	Operator	r and Well								
Opera	tor name addre	Buriingto		es Oil and Gas gton, NM 8749				OGRID Number 014538		
Contact Party Maralene Spawn								Phone 505/326-9700		
	erty Name	JNIT			Well Num			API Number 3004531230		
UL	Section	Township	Range	Feet From The		Feet From The		County		
0	11	32 N	7 W	1640 F	FSL	1540	FEL	SAN JUAN FE 6 70		
II.	Worko	ver						(3 × 30 / 6 g)		
Date Workover Commenced 05/07/2005					Previous Producing Pool(s) (Prior to Workover): BASIN FRUITLAND COAL (GAS)			ON CONTROL		
Date V	Vorkover Comp	eleted:	06/03/2005					ON CONSON		
V.	Arii	County Mare 1. I a 2. I i av 3. To	nave made, or ailable for this the best of m rve and/or tab) tor, or authorized re r caused to be mad Well. by knowledge, this a	epresenta le, a dilige application	ent search of the p	or, of the above production rec			
		ature/Ma	ralene	1	-Title <u>Sr</u>	ay of	Date <u>///e//</u>	<u>rle</u>		
	My C	Commission e	xpires: //5/200	08		Notar	y Public) Talir	icia L. Cleight		
	V. CE Th Di Sec	ERTIFICATION is Application vision hereby cretary of the	ON OF APPE is hereby ap verifies the of Taxation and	proved and the ab lata shows a positi	ve produc	ction increase. B	ignated a Wel	I Workover Project and the the Division notifies the his Well Workover Project		
ſ		Sistrict Super				District 77FC =		01-17-2006		

VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT:

REG_DTL_D	BASIN FRUITLAND COAL (GAS)	
06/01/2004	22365	
07/01/2004	20945	
08/01/2004	26286	
09/01/2004	26106	
10/01/2004	27720	
11/01/2004	26744	
12/01/2004	26323	
01/01/2005	25096	
02/01/2005	22986	
03/01/2005	24417	
04/01/2005	22946	
05/01/2005	937	
06/01/2005	18770	
07/01/2005	39328	
08/01/2005	48656	
09/01/2005	47512	

Submit 3 Copies To Appropriate Distric									
	t Sta	ite of New Me	xico /		Form C-103				
Office District I 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources WELL API NO.									
1625 N. French Dr., Hobbs, NM 88240									
District II	OII CON	DIVISION	30	-045-31230					
1301 W. Grand Ave., Artesia, NM 8821	•			5. Indicate Type of Lease					
District III 1000 Rio Brazos Rd., Aztec, NM 87410		South St. Fran		STATE ☐ FEE ☒					
District IV	Sa	nta Fe, NM 87	505	6. State Oil & Gas Lease No.					
1220 S. St. Francis Dr., Santa Fe, NM									
87505									
	TICES AND REPOR			7. Lease Name of	r Unit Agreement Name				
(DO NOT USE THIS FORM FOR PRO				1					
DIFFERENT RESERVOIR. USE "API PROPOSALS.)	PLICATION FOR PERMIT	I" (FURM C-101) FU	K SUCH		Ilison Unit				
1. Type of Well:		المتر فيستند والمارا	-	8. Well Number					
	X Other		10 g		#124S				
		/	- 1/2 A	0.00000.11					
2. Name of Operator		104 5000		9. OGRID Numl	per				
Burlington Resources Oil & G	as Company LP	10%		14538					
3. Address of Operator			() ()	10. Pool name o					
P.O. Box 4289, Farmington, N	M 87499-4289	2 6 -	1	Basin Fruitland C	Coal - 71629				
4. Well Location	P.	المستعمل المينة							
	\	V2.	1		l l				
Unit Letter O:	1640' feet from	the A South	🚉 🗹 line and	1540 feet from the	<u>East</u> line				
		C.L.D.	<u> </u>						
Section 11	Township	32N R	ange 7W NMP	M San Juan	County				
			RKB, RT, GR, etc.						
			,,						
12. Check Appropriate Box	r to Indicate Natur	re of Notice R	enort or Other I)ata	STANDARD CONTRACTOR CO				
12. Check Appropriate Box	A to maicate matu	ic of Motice, in	opon or outer i	rata					
NOTICE OF	INTENTION TO	•	SUB	SEQUENT RE	PORT OF				
PERFORM REMEDIAL WORK			REMEDIAL WOR		ALTERING CASING				
PERIORIA REMEDIAL WORK	L LEGG AND ADA	MIDON L	TILIVILDIAL WON	`	ALIEMING CASING [
TEMPORARILY ABANDON	☐ CHANGE PLAN	s 🗇	COMMENCE DR	LLING OPNS 🗆	PLUG AND				
TEMPORALET ABARDON	OHARGETEAN	٥ ۵	OCIVINICIACE DIVI	LENIAG OF NO.	ABANDONMENT				
PULL OR ALTER CASING	☐ MULTIPLE		CASING TEST A	ND 🗆	ADAINDONNIEN				
	COMPLETION	_	CEMENT JOB	_					
OTHER:			OTHER: Reca	vitation	$oldsymbol{\boxtimes}$				
		Clearly state all r	ertinent details, an	d give pertinent dat	es including estimated date				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date									
			le Completions: At		ram of proposed completion				
of starting any proposed			le Completions: At		ram of proposed completion				
			le Completions: At		ram of proposed completion				
of starting any proposed or recompletion.	work). SEE RULE 1	103. For Multip	•	tach wellbore diag					
of starting any proposed or recompletion. 5/7/05 MIRU Aztec #469. ND W	work). SEE RULE I	. TOH & LD w/h	anger & tbg. Spea	tach wellbore diag	r't pull. Use jet cutter & cut				
of starting any proposed or recompletion. 5/7/05 MIRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had	. TOH & LD w/h to cut liner off @	anger & tbg. Spea 3230'. COOH w/4	tach wellbore diag r into liner & couldr ts & cut off jt of line	n't pull. Use jet cutter & cut or. RIH w/mill to 3126'				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil	. TOH & LD w/h to cut liner off @ lled liner. TOH w	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest	tach wellbore diag r into liner & couldr ts & cut off jt of line of liner. LD fishing	n't pull. Use jet cutter & cut or. RIH w/mill to 3126' I tools. PU & RIH w/9-1/2"				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to	. TOH & LD w/h to cut liner off @	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis	tach wellbore diag r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, J	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to I-55 pre-perf'd liner an	TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surged set @ 3309' w.	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to I-55 pre-perf'd liner an	TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surged set @ 3309' w.	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, J	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to I-55 pre-perf'd liner an	TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surged set @ 3309' w.	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, J	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to I-55 pre-perf'd liner an	TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surged set @ 3309' w.	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, J	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to I-55 pre-perf'd liner an	TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surged set @ 3309' w.	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, J	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to I-55 pre-perf'd liner an	TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surged set @ 3309' w.	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. I tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, J	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' – 3245'. RU to I-55 pre-perf'd liner an	TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surged set @ 3309' w.	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to I-55 pre-perf'd liner an RIH w/pump & rods.	TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge Sand Sand Sand Sand Sand Sand Sand Sand	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH & released rig 6/2/0	tach wellbore diag r into liner & couldr its & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5	n't pull. Use jet cutter & cut or. RIH w/mill to 3126' g tools. PU & RIH w/9-1/2" gprox. 7 days C/O to TD. 5 tbg (54 jts) and landed @				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foamunderreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had ar & mist. C/O fill. Mil n 3214' - 3245'. RU to l-55 pre-perf'd liner an RIH w/pump & rods.	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surget set @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr its & cut off it of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 5.	o't pull. Use jet cutter & cut or. RiH w/mill to 3126' or tools. PU & RiH w/9-1/2" or certify that any pit or below-				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had ar & mist. C/O fill. Mil n 3214' - 3245'. RU to l-55 pre-perf'd liner an RIH w/pump & rods.	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surget set @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr its & cut off it of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 5.	o't pull. Use jet cutter & cut or. RiH w/mill to 3126' or tools. PU & RiH w/9-1/2" or certify that any pit or below-				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. Itagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informating grade tank has been/will be constructed.	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had ar & mist. C/O fill. Mil n 3214' - 3245'. RU to l-55 pre-perf'd liner an RIH w/pump & rods.	. TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surge d set @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 5.	a't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD. 5 tbg (54 jts) and landed @ oper certify that any pit or belownative OCD-approved plan □.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foamunderreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had ar & mist. C/O fill. Mil n 3214' - 3245'. RU to l-55 pre-perf'd liner an RIH w/pump & rods.	. TOH & LD w/h to cut liner off @ lled liner. TOH wo surge well. Surge d set @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 /taper tap, had rest ged w/air/ foam/mis /TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr ts & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 5.	o't pull. Use jet cutter & cut or. RiH w/mill to 3126' or tools. PU & RiH w/9-1/2" or certify that any pit or below-				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. Itagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informating grade tank has been/will be constructed.	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to 1-55 pre-perf'd liner an RIH w/pump & rods. on above is true and of d or closed according to N	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge well. Surge dest @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr its & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 e and belief. I furtl or an (attached) alter	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' of tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD. 5 tbg (54 jts) and landed @ oper certify that any pit or belownative OCD-approved plan .				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. Itagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informati grade tank has been/will be constructed.	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to 1-55 pre-perf'd liner an RIH w/pump & rods. on above is true and of d or closed according to N	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge well. Surge dest @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr its & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 e and belief. I furtl or an (attached) alter	a't pull. Use jet cutter & cut or. RIH w/mill to 3126' or tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD. 5 tbg (54 jts) and landed @ oper certify that any pit or belownative OCD-approved plan □.				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informating grade tank has been/will be constructed SIGNATURE Type or print name Patsy	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to 1-55 pre-perf'd liner an RIH w/pump & rods. on above is true and of d or closed according to N	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge well. Surge dest @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr its & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 e and belief. I furtl or an (attached) alter	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' of tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD. 5 tbg (54 jts) and landed @ oper certify that any pit or belownative OCD-approved plan .				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. Itagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informating grade tank has been/will be constructed.	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to 1-55 pre-perf'd liner an RIH w/pump & rods. on above is true and of d or closed according to N	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge well. Surge dest @ 3309' w Spaced out. RD	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr its & cut off jt of line of liner. LD fishing t and naturally for a w/2-3/8", 4.7#, J-5 e and belief. I furtl or an (attached) alter	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' of tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD. 5 tbg (54 jts) and landed @ oper certify that any pit or belownative OCD-approved plan .				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informating grade tank has been/will be constructed SIGNATURE Type or print name Patsy	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to 1-55 pre-perf'd liner an RIH w/pump & rods. on above is true and of d or closed according to N	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge well. Surge dest @ 3309' w Spaced out. RD Complete to the bear of the bear of the surge well. TITLE Surge well.	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0 est of my knowledg , a general permit	r into liner & couldr its & cut off jt of line of liner. LD fishing and naturally for a w/2-3/8", 4.7#, J-5 e and belief. I furtl or an (attached) alter alist DATE Telephone No.	a't pull. Use jet cutter & cut br. RIH w/mill to 3126' g tools. PU & RIH w/9-1/2" approx. 7 days C/O to TD. 5 tbg (54 jts) and landed @ her certify that any pit or below- native OCD-approved plan □. 6/16/05				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informating grade tank has been/will be constructed SIGNATURE Type or print name Patsy	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to 1-55 pre-perf'd liner an RIH w/pump & rods. on above is true and of d or closed according to N	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge well. Surge dest @ 3309' w Spaced out. RD Complete to the bear of the bear of the surge well. TITLE Surge well.	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0	r into liner & couldr its & cut off jt of line of liner. LD fishing and naturally for a w/2-3/8", 4.7#, J-5 e and belief. I furtl or an (attached) alter alist DATE Telephone No.	o't pull. Use jet cutter & cut or. RIH w/mill to 3126' of tools. PU & RIH w/9-1/2" opprox. 7 days C/O to TD. 5 tbg (54 jts) and landed @ oper certify that any pit or belownative OCD-approved plan .				
of starting any proposed or recompletion. 5/7/05 MiRU Aztec #469. ND W liner @ 3261'. Had to fish liner. It tagged fill. Circ. hole w/air, foame underreamer. Underreamed from 6/1/05 RIH w/8 jts, 5-1/2" 15.5#, 3258'. ND BOP, NU WH. 6/2/05 I hereby certify that the informating grade tank has been/will be constructed. SIGNATURE Type or print name Patsy (This space for State use)	work). SEE RULE I H & NU BOP, PT-OK Fished for 5 days had er & mist. C/O fill. Mil n 3214' - 3245'. RU to 1-55 pre-perf'd liner an RIH w/pump & rods. on above is true and of d or closed according to N	. TOH & LD w/h to cut liner off @ lled liner. TOH w o surge well. Surge well. Surge well. Surge dest @ 3309' w Spaced out. RD Complete to the bear of the bear of the surge well. TITLE Surge well.	anger & tbg. Spea 3230'. COOH w/4 //taper tap, had rest ged w/air/ foam/mis/TOL @ 3005'. TIH & released rig 6/2/0 est of my knowledg , a general permit	r into liner & couldr its & cut off jt of line of liner. LD fishing and naturally for a w/2-3/8", 4.7#, J-5 e and belief. I furtl or an (attached) alter alist DATE Telephone No.	a't pull. Use jet cutter & cut br. RIH w/mill to 3126' g tools. PU & RIH w/9-1/2" approx. 7 days C/O to TD. 5 tbg (54 jts) and landed @ her certify that any pit or below- native OCD-approved plan □. 6/16/05				