

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0137  
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

XTO ENERGY INC.

3a. Address

2700 Farmington Ave., Bldg. K, Ste 1 Farmington,

3b. Phone No. (include area code)

505-324-1090

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1,310' FSL & 2,190' FEL, Unit O, Sec 20, T-27-N, R-8-W

5. Lease Serial No.

NMM 03380

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Florance D LS #4A

9. API Well No.

30-045-29258

10. Field and Pool, or Exploratory Area

Blanco Mesaverde

11. County or Parish, State

San Juan NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- |   |  |  |   |
|---|--|--|---|
| <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen                      | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat              | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction            | <input type="checkbox"/> Recomplete                | <input type="checkbox"/> Other _____    |
| <input type="checkbox"/> Change Plans         | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |   |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back                   | <input type="checkbox"/> Water Disposal            |   |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy plugged & abandoned this well in the following manner:

MIRU serv rig. MI WLJ. ND WH. NU BOP. MIRU CTU. POH w/CT, SN, ck vlv. RDMO CTU. Ppd dwn csg w/20 BFW & KW. ND WH; NU BOP. MIRU WLJ. RIH w/CIRP @ set @ 4952'. TIH w/tbg. Plug #1: 17 sx Type III cmt (14.8 ppg, 1.32 cuft/sx). Ppd dwn tbg w/3.4 bbls cmt. Cmt fr/4952'-4262'. BOT @ 3786'. Plug #2: 7 sx Type III cmt (14.8 ppg, 1.32 cuft/sx). Ppd dwn tbg w/1.4 bbls cmt. cmt fr/3786'-3502'. BOT @ 3201'. Plug #3: Cmt 15 sx Type III cmt (14.8 ppg, 1.32 cuft/sx). Ppd dwn tbg w/3 bbls cmt. Cmt fr/3201'-2592'. BOT @ 2594'. Plug #4: 7 sx Type III cmt (14.8 ppg & 1.32 cuft/sx). Ppd dwn tbg w/1/4 bbls cmt. Cmt fr/2554'-2270'. MIRU WLJ. Perfd 2 holes @ 21/05'. Ppd dwn csg & estb circ. Circ cln. ND BOP. NU WH. RIH w/chem cutter. TOH w/csg. Plug #5: 36 sx type III cmt (14.8 ppg, 1.32 cuft/sx). Ppd dwn csg w/7.2 bbls cmt. Cmt fr/2100'-1754'. Plug #6: 18 sx Type III cmt (14.8 ppg, 1.32 cuft/sx). Ppd dwn csg w/3.6 bbls cmt. Cmt fr/718'-545'. BLM rqstd perfs @ 50'. Perfd 3 sqz holes @ 50'. Ppd 1/4 BW. Pess to 1000 psig. Bled off to 0 psig in 1 min. Tried 3 times; same results. BLM rqstd perfs @ 20'. Perfd 3 sqz holes @ 20'. Estb circ fr/BH w/1/8 BW. TIH w/csg to 187'. Plug #7: 29 sx Type III cmt (14.8 ppg, 1.32 cuft/sx). Ppd dwn csg w/3.6 bbls cmt. Cmt fr/187' to surf. Circ good cmt fr/csg glg w/23 sx. Circ out cmt fr/BH vlv w/6 sx. TOH w/csg. ND BOP. Dig out WH. Cut off. Installed dry hole marker. Cmted w/15 sx Type III cmt. RDMO P&A rig.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

BILLY C. PERKINS

Title

per HP/ P&A 1-13-06  
REGULATORY COMPLIANCE TECH

Date 1/20/2006

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.